

Not Noted  
Pruning After Rain  
3 day

3 day

LKIC tennehr

VEHICLE NO.: SGV 580 T

X  
X

400  
X  
X  
400

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.