

ALG (LIS)

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.02.2021

Time: 12:01:02

Page: 1

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305454788
REGN NO : SH 7012C
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 25.05.2017
DATE/TIME IN : 22.02.2021 10:30
ACCIDENT DATE : 19.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0302-2292-A	COVER FRONT BUMPER	1	499.90	25.00	374.92	X
0002 04-01-0302-0574-A	FENDER SUB-ASSY FRONT LH	1	945.30	25.00	708.97	X
0003 03-01-0302-2020-G	WHEEL DISC	1	1,570.55	25.00	1,177.91	X
0004 04-01-0302-2297-G	EMBLEM SIDE PANEL (HYBRID	1	86.50	25.00	64.87	✓

SUB-TOTAL : 2,326.67

JOB NATURE

0000 PB	PANEL BEATING	800.00	350
0001 SP	SPRAYPAINT CHARGE	600.00	250 Saw
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	X NV

SUB-TOTAL : 1,450.00

TOTAL : 3,776.67

MVA NAME & SIGNATURE
DATE: 22/2/21

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE:

2x Day
o/p L/S \$750.00
After repair photo.
Gmo Qianp
22/2/21 3pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: