

ASS. REC. BY: *GA*

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SHD 7295D
 at Workshop m/s Comfort Layang
 of _____
 Insured: SMW 1119K
 Policy No. MS000953
 Claims No. M2100891
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SHD 7295D Yr Regn: 06 Dec 2018
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prins c.c. 1798
 Colour: Blue A/C: Insured / Std / NI / NA
 Sp. Reading: 312 890 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKB3FU103077540
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD / Rim or
 Tyre Size: F: 195/65R15
 R: 11

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
	<u>0</u>

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or westlake
 Front 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 2202-21
 Survey held at w/s 3:45 pm
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
10/03/21	@4.42pm revised to Fiona Gan via Merimen.
15/6/2021	Confirmed final fig P/P \$1779.94, 2 repair days. (RED \$1701.02; 49%)

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 15/6 TYPIST
 Date/Time, File Return to?
 2)

Days Of Repair: 2
 Resurvey No. of Trip: 1

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Insp (\$)
 : Misc. Insp (\$)

Survey Fee: _____
 Transportation: _____
 Photos: _____
 Other: _____
 Total: _____

Report Formed: TP
 Total Amount: \$1779.94

COMFORTDELGRO ENGINEERING PTE LTD

Date: 22.02.2021

REPAIR ESTIMATE

Tokio Marine CP/10

Time: 14:53:15

Page: 1

TS

Lkk - Guo Qiang

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305455006
REGN NO : SHD7295D
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(G4)
DATE OF REGN : 06.12.2018
DATE/TIME IN : 22.02.2021 12:55
ACCIDENT DATE : 22.02.2021

Tyre Brand: Westlake

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT	REMARKS
0001	04-01-0302-2282-G	REAR BUMPER	1	458.60 25.00 343.95	Re
0002	04-01-0302-2287-G	REAR BUMPER CENTER GUARD	1	552.60 25.00 414.45	X Re
0003	04-01-0302-2288-G	REAR BUMPER REINFORCEMENT	1	318.80 25.00 239.10	X NN
0004	04-01-0302-2965-G	REAR BUMPER EXTENSION RH	1	232.00 25.00 174.00	✓ BR
0005	04-01-0302-3937-G	REAR BUMPER RETAINER RH	1	112.70 25.00 84.52	Re
0006	04-01-0302-2286-G	REAR BUMPER TOW COVER	1	82.70 25.00 62.02	X ✓ CUT
0007	04-01-0302-0585-A	TAILLAMP UPR RH	1	557.90 25.00 418.42	X NN
0008	04-01-0302-0795-A	TAILLAMP LWR RH	1	548.40 25.00 411.30	X NN
0009	04-01-0302-2267-G	REAR BUMPER CLIPS	10	22.00 25.00 16.50	X X NN
0010	09-01-0302-2005-A	REVERSE SENSOR	1	135.70 135.70	X NN
0011	04-01-0302-1150-A	REAR BUMPER MAT	1	50.00 50.00	MC
				SUB-TOTAL	: 2,349.96 1128.94

JOB NATURE

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Tokio Marine
C/P

LKK - Guo Qiang

Date: 22.02.2021

Time: 14:53:15

Page: 2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305455006
REGN NO : SHD7295D
MILEAGE : 0000000000
MAKE : TOYOTA
MODEL : PRIUS HYBRID(C
DATE OF REGN : 06.12.2018
DATE/TIME IN : 22.02.2021 12:55
ACCIDENT DATE : 22.02.2021

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 PB PANEL BEATING	400.00		350		
0001 SP SPRAYPAINT-Rear Fender RH Etc	600.00		250		
0002 L R/I REVERSE SENSOR	120.00		40		
0003 20-05 TP MERIMEN	11.00		/		
SUB-TOTAL :					1,131.00
TOTAL :					3,480.96
					1779.94

MVA NAME & SIGNATURE
DATE :

Limfi

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

2 Pray 3.
P/P
before paint photos.
Guo Qiang
22/2/21
3:45 pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: