

ASS. REC. BY: Sun Pin

REF:

CS/MSG21002469/GtfzDenma**ASSIGNMENT**

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SKM 39845Yr Regn: 28/11/2016Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volvo v40 T2c.c. 1498Colour: Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 72413

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YV/MV28H0H2390735Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45 R18R: 225/45 R18BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 6 mm /R/Bal. 6 mmL/Bal. 6 mmL/Bal. 6 mmD.O.A. 18/02/2021D.O.I. 22/02/2021

Survey held at

vin's Auto.Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: 65,000

PV: 44,278

NV: 20,722.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

S + RS. \$ _____

Photos _____

Others _____

Rep. Format: _____

Lump Sum / L.B. (\$ _____)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	060H
Vehicle Details	
Vehicle No.:	SKM39845
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Feb 2021
Vehicle Make:	VOLVO
Vehicle Model:	V40 T2 (A)
Primary Colour:	Blue
Manufacturing Year:	2016
Engine No.:	B4154T51824251
Chassis No.:	YV1MV28H0H2399735
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$23,513.00
Original Registration Date:	28 Nov 2016
First Registration Date:	28 Nov 2016
Transfer Count:	0
Actual ARF Paid:	\$19,919.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Nov 2026
PARF Rebate Amount:	\$14,939.00
Intended COE Rebate Details	
COE Expiry Date:	27 Nov 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,951.00
COE Rebate Amount:	\$29,395.00
Total Rebate Amount:	\$44,334.00

The information contained herein is correct as at 20 Feb 2021

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/02/2021 17:24 (SGT)
Date of Accident	18/02/2021 14:40 (SGT)
Exact Location of Accident	Near 81 Tampines Ave 1, Singapore 528685
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKM3984S
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	AYOOB YACOOB ANGULLIA
NRIC No	SXXXX060H
Email Address	SHAHIRAH.ANGULLIA@GMAIL.COM
Mobile Phone No	(Phone) +65-91015110
Alternative Phone No	+65-91015110

VEHICLE PARTICULARS

Manufacturer	Volvo
Model	V40 T2 (A)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DHOM110154151604
Cover Note Number	-

DRIVER

Name of Driver	SHAHIRAH AYOOB ANGULLIA
NRIC No	SXXXX708D
Date Of Birth	17/03/1984
Occupation	Indoor

Date Of Driving Pass	10/03/2009
Driving experience	11 YEARS AND 11 MONTHS
Gender	Female
Mobile Number	(Phone) +65-90226443
Alt. Phone Number	-
Email Address	SHAHIRAH.ANGULLIA@GMAIL.COM
Address	BLK 77 FLORA DRIVE #04-21
Address complement	-
Postcode	506884
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Child
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Change/cross lane
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	DAUGHTER
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO THE SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	XE3054P
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Goods vehicle
Name of Driver	ONG NIAP BOON
NRIC No	SXXXX863E

Contact Number	(Phone) +65-91473931
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	SHAHIRAH AYOOB ANGULLIA
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKM3984S
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time

Witnessed by Reporting Centre
Personnel



Sketch Plan



A = SKM 3984S

B = XE 3054P

Describe Circumstances of the Accident

On 18 Feb 2021 at around 14:40 hrs. I was driving straight on my lane at along Tampines Avenue 10. Suddenly I felt an impact from my right side. The lorry XE3054P crossed into my lane and hit onto my vehicle. After the impact, I tried very hard to stabilize my steering. Otherwise my vehicle would have lost control. My vehicle also swerved for few meters after the impact hit onto my vehicle. After that the driver alighted from his lorry, he mentioned that he didn't notice my vehicle and he admitted his fault.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/022021/4729
Accident date: 18/2/2021
Your Ref : XE3054P

Tax Invoice:
Date : 20/2/2021

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKM3984S
Model : VOLVO V40 T2 (A)

		Parts Prices
1 pc	Rear RH door / DD	\$ 2,040.60
1 pc	Rear RH door rubber / Nec	\$ 127.50
1 pc	Rear RH door outer moulding / Nec	\$ 118.40
1 pc	Rear RH fender / CRU	\$ 1,355.70
1 pc	Rear RH fender quarter glass moulding with glass / Nec	\$ 448.60
1 pc	Rear RH taillamp X / CRA	\$ 407.00
1 pc	Rear bumper / CRU	\$ 1,531.20
1 pc	Rear bumper RH side retainer / BK	\$ 93.30
10 pcs	Rear bumper clips @ \$6.10 / Nec	\$ 61.00
1 pc	RH side skirt X X / CRU	\$ 534.40
1 pc	Rear RH wheel sport rim / SCR	\$ 648.50
1 pc	Rear RH wheel shock absorber ? X	\$ 227.70
1 pc	Rear RH wheel knuckle arm ? / BT	\$ 695.30
1 pc	Rear RH wheel knuckle arm bearing ? / Jam	\$ 462.60
1 pc	Rear RH wheel top arm ? / BT	\$ 183.50
1 pc	Rear RH wheel lower arm (big) ? / BT	\$ 511.70
1 pc	Rear RH wheel lower arm (small) ? / BT	\$ 151.20
1 pc	Rear RH wheel side control arm ? X	\$ 711.30
1 pc	Rear crossmember ? / BT	\$ 1,911.20
		<hr/>
		\$ 12,220.70
Less 5%		\$ (611.04)
		<hr/>
		\$ 11,609.67

1 pc	Rear RH fender quarter glass gum / Nec	\$ 60.00	N 30
1 pc	Rear RH wheel tyre X	\$ 380.00	N


Our Ref : TP/022021/4729
Accident date: 18/2/2021
Your Ref : XE3054P

Tax Invoice:

Date : 20/2/2021

Towing (inv.) X	\$ 150.00 150
To check wheel alignment	\$ 150.00 60
To remove and refix rear undercarriage	\$ 380.00 200
To remove and refix petrol tank	\$ 120.00 60
To remove and refix seat cushion and roof lining	\$ 280.00 100
To repair rear damages	\$ 1,200.00 800 900
To spray painting	\$ 1,300.00 400 1,000
	<u>\$ 15,629.67</u>

VIN'S MOTOR PTE LTD



Repair dy - 7 days

~~PIP~~ PIP

before ~~After~~ paint photo

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sunpin(HK)

22/02/2021

TP without prejudice

Sunpin@lkkauto.com

8661 2621



AUTOMOTIVE GROUP

A Sin Ming Autocity,
160 Sin Ming Drive #03-03
Singapore 575722
T 6453 2121 (4 lines) / 6458 1111 (24 hrs)
F 6459 9795 / 6459 0433
E admin@vinsautogroup.com.sg
W www.vinsautogroup.com.sg

Our Ref : TP/022021/4729
Accident date: 18/2/2021
Your Ref : XE3054P

Tax Invoice:
Date : 20/2/2021

Motor Claim Department
MSIG INSURANCE (SINGAPORE) PTE LTD
No.4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

ESTIMATE COST OF REPAIRS TO

Vehicle No. : SKM3984S
Model : VOLVO V40 T2 (A)

	Parts Prices
1 pc Rear RH door / DD	\$ 2,040.60
1 pc Rear RH door rubber / NRC	\$ 127.50
1 pc Rear RH door outer moulding / NRC	\$ 118.40
1 pc Rear RH fender / CRV	\$ 1,355.70
1 pc Rear RH fender quarter glass moulding with glass / NRC	\$ 448.60
1 pc Rear RH taillamp X / CRA	\$ 407.00
1 pc Rear bumper / CRV	\$ 1,531.20
1 pc Rear bumper RH side retainer / BK	\$ 93.30
10 pcs Rear bumper clips @ \$6.10 / NRC	\$ 61.00
1 pc RH side skirt X / CRV	\$ 534.40
1 pc Rear RH wheel sport rim / SCR	\$ 648.50
1 pc Rear RH wheel shock absorber ? X	\$ 227.70
1 pc Rear RH wheel knuckle arm ? / BT	\$ 695.30
1 pc Rear RH wheel knuckle arm bearing ? / Jam	\$ 462.60
1 pc Rear RH wheel top arm ? / BT	\$ 183.50
1 pc Rear RH wheel lower arm (big) ? / BT	\$ 511.70
1 pc Rear RH wheel lower arm (small) ? / BT	\$ 151.20
X 1 pc Rear RH wheel side control arm ? X	\$ 711.30
1 pc Rear crossmember ? / BT	\$ 1,911.20
	<hr/>
	\$ 12,220.70
Less 5%	\$ (611.04)
	<hr/>
	\$ 11,609.67
1 pc Rear RH fender quarter glass gum / NRC	\$ 60.00 N 30
1 pc Rear RH wheel tyre X	\$ 380.00 N