



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:PETER		Ref: CC4/ASM21002472/Kps3q2 Date: 15/04/2021 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLM 6368P	Veh. Inspected	GBD 2764X
Policy No.	VCX/P1930117	Coverage (\$)	0.00
Claim No.	S1M033IP	Excess (\$)	0.00
Assign From		Assign Date	22/02/2021
2. Vehicle Particulars & Condition			
Make & Model	NISSAN CABSTAR (M)	c.c	2953
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JN1SC2F24Z0856184	Colour	SILVER
Odometer	121563 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15X8	TOYO	9 mm
L/H Front Tyre	195 R15X8	TOYO	9 mm
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	9/9 mm
L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	9/9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	19/02/2021	Inspection Date	23/02/2021
Survey held at	GUAN MOTOR WORKS 176 SIN MING DRIVE #02-03 SIN MING AUTOCARE SINGAPORE 575721		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	