

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 19.02.2021

Time: 11:10:27

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

JOB NO : 305454436
 REGN NO : SHC7226J
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 28.07.2016
 DATE/TIME IN : 18.02.2021 23:00
 ACCIDENT DATE : 18.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-2322-A	FRT BUMPER	1	1,052.20	20.00	841.76	/ CA 22
0002 04-01-0103-2164-A	RADIATOR GRILLE	1	1,480.00	20.00	1,184.00	/ CA
0003 04-01-0103-2175-G	RADIATOR GRILLE H EMBLEM	1	129.50	20.00	103.60	/ 162
0004 04-01-0103-0781-A	HEADLAMP LH	1	1,800.00	20.00	1,440.00	/ CA BR
0005 04-01-0103-0574-A	FRT FENDER LH	1	663.00	20.00	530.40	X Repair
0006 04-01-0103-0637-G	FRT BUMPER UPR BRKT LH	1	22.40	20.00	17.92	?
0007 04-01-0103-0639-G	FRT BUMPER BRKT LH	1	24.60	20.00	19.68	?
0008 04-01-0103-4891-G	FRT BUMPER GRILLE LH	1	187.30	20.00	149.84	/ CA

SUB-TOTAL : 4,287.20

JOB NATURE

0000 PB	PANEL BEATING	600.00	280
0001 SP	SPRAYPAINT-Bonnet ETC	900.00	500
0002 17-01	CHECK ALL LIGHTING	40.00	30

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

NTUC-(45)

Date: 19.02.2021

Time: 11:10:27

Page: 2

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)

CUSTOMER: 7010070

ADDRESS : CITYCAB PTE LTD

383 SIN MING DRIVE

SINGAPORE SINGAPORE 575717

65551188

LKK -

JOB NO : 305454436
REGN NO : SHC7226J
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 28.07.2016
DATE/TIME IN : 18.02.2021 23:0
ACCIDENT DATE : 18.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0003 20-00 TUFF COAT ON AFFECTED PARTS.

40.00 X NN

0004 23-01 TOWING FEE

0.00

SUB-TOTAL : 1,580.00

TOTAL : 5,867.20

Lmf

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

3 Days.

Lump sum repair

After repair photos.

Amo Qiang

19/2/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: