

Actual (L/S)

COMFORTDELTA ENGINEERING PTE LTD

Date: 22/02/2021

REPAIR ESTIMATE

Time: 13:53:48

Page: 1

COMPANY: THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS: COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 375717
65508755

JOB NO: 105455003
REGN NO: SHA7506L
MILEAGE: 000000000
MAKE: MERCEDES BENZ
MODEL: E220CDIE(E6)
DATE OF REGN: 28/05/2015
DATE/TIME IN: 22/02/2021 10:50
ACCIDENT DATE: 22/02/2021

JOB: PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0202-2033-G	FRT BUMPER ASSY	1	1,890.50	20.00	1,512.40	✓ Cut
0002 04-01-0202-0574-G	FRT FENDER LH	1	966.08	20.00	772.86	✓ bue
0003 04-01-0202-2004-G	TYRE RIM	1	1,250.00	20.00	1,000.00	✓ cut

SUB-TOTAL : 3,285.26 ✓

JOB NATURE

0000 PB	PANEL BEATING	900.00	800
0001 SP	SPRAYPAINT CHARGE	600.00	500
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00	40

SUB-TOTAL : 1,550.00

TOTAL : 4,835.26 4625.26

MECHANIC NAME & SIGNATURE

DATE: 22/2/21

AUTHORISED: YES / NO

SURVEYOR NAME & SIGNATURE

DATE:

-20%: 3700

4 Days.
L/S
After repair photos.
Gave Receipt
22/2/21 3:15pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: