NA2 | REF: CU4 AIG 2002499 / NBA3 | LKE

ASSIGNMENT

Date:

Estimated Cost:

Claim Type: MD / NER / OD RES / EVA / INV / MV

Impacted Vehicle No:

Excess:

Veh No: SHA 3891A | Yr Regn: 22/OCT/2019

Type: M.Car / M.Cycle / BUS / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: HYUNDAI IONIQ G3 | cc 1,581

Colour: BLUE | A/C: Insd'd / Std / NI / NA

Sp Reading: 186,679 | T/Belt: Insured / Std / NI / NA

Engine:

Chas: KMHC851CVLU186596

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Jammed / Locked / Burnt or

Brake: Jammed / Locked / Burnt or

Wheels: NI / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 11

N/S | O/S

BUS / CUT / EXHOVA / GY / FS / LZA / WC / OMSU / PR / SC / ...

TOYO / YOKO or WESTLAKE (F), DAVANTI (R)

Tread: F/Bal: 4 mm | R/Bal: 4

R/Bal: 4 mm | L/Bal: 4

DOA: 22/02/2021 | DOI: 23/02/2021

Survey Held at: CDGE LOYANG

Det. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Tow U/C / Chassis frame / Body Structure / Wheels / Axles

AIG PIP

Action / Instructions

Days Of Repair:

Reservoy No. of Trip:

Prelim. Report

Final Report

Add Fee: Site Insp. (S$)

Design/Sw (S$)

Tech. Inv. (S$)

Weekend (S$)

Survey Fee:

Transportation

Total