



RM 41 990

Kuala Lumpur

Used
2010 ✓ Verified90000 - 94999
1799ccHonda CIVIC 2.0 FACELIFT (A) MCO WE HAVE OPEN
RM 49 800

Today, 14:05

Kuala Lumpur

Used
2010 ✓ Verified80000 - 84999
1998ccHonda CIVIC 1.8 i-VTEC (A)
RM 36 900

Today, 13:28

Pahang

Used
2010 ✓ Verified85000 - 89999
1799ccHonda CIVIC 1.8 S i-VTEC FACELIFT (A) LEATHER
RM 38 800


Today, 12:40

Selangor

Used
20xx ?80000 - 84999
1799ccHonda CIVIC 1.8 i-VTEC (A) FACELIFT 1 OWNER
RM 41 800

Today, 12:20

Pahang

Used
2010 ✓ Verified85000 - 89999
1799ccHonda CIVIC 2.0 (A) MUGEN RR KIT K20 FD2R FD2
RM 45 800

Today, 12:20

Kuala Lumpur

Used
20xx ?95000 - 99999
1998ccHonda CIVIC 1.8 S i-VTEC (A) MUGEN RR BODY KIT
RM 38 800

Today, 11:30

Kuala Lumpur

Used
20xx ?120000 - 129999
1799ccHonda CIVIC 1.8 S i-VTEC (A) TIPTOP CONDITION
RM 36 800


Today, 11:30

Kuala Lumpur

Used
20xx ?110000 - 119999
1799ccHonda CIVIC 1.8 S i-VTEC FACELIFT (A)
RM 38 888

Today, 11:15

Selangor

Used
20xx ?100000 - 109999
1799ccHonda CIVIC 1.8 FACELIFT (A) 1 OWNER ACCIDENT FREE
RM 38 800

Today, 10:50

Kuala Lumpur

Used
2010 ✓ Verified95000 - 99999
1799cc



Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

CONTINUATION OF REPORT

Driver			
Name	YAP WAI YEE	ID No.	G7565161P
Related Vehicle	NIL	Contact No.	81105949
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight

Brief Details.

On 3/2/2021 at around 1320hrs, I was driving my Malaysian vehicle bearing Malaysian plate number (JMN5949) along Mackenzie Road towards Bukit Timah Road. I stopped at the junction before turning left onto Bukit Timah Road, after I stopped my vehicle I felt a huge impact. I then came down of my vehicle, and saw that another car bearing plate number (SJQ5152D) hit onto the rear of my vehicle.

The driver of the other vehicle approached me and asked me if I'm fine. We then exchanged particulars, we then came to an agreement to settle via insurance. I then left shortly after and drove to the nearby workshop.

I wish to state that due to the impact, I suffered pain on my neck area. I will be going to see the doctor after lodging this report.

I wish to state that there were no police or ambulance that attended to us.

I am lodging this report as I will be filing this report to my insurance.

Details of the damages to my vehicles as follows:

- Right rear bumper dislodged
- Rear right tail light damaged
- Suspension damaged



**SINGAPORE
POLICE FORCE**



T/20210203/2087

Police Station Of Origin:
Eunos NPP
629 Bedok Reservoir Road #01-1620
SINGAPORE 470629
Tel No: 1800-4439999

3 of 3

Report No. T/20210203/2087

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: G / Sgt 1 WONG KOK WAI <i>Wkw</i>	Signature Of Informant: 
Signature Of Interpreter: Not applicable	Date/Time: 03/02/2021 15:31
Officer In Charge Of Case: TP / GIA / Staff Sgt WONG SIEU LUI Contact No.: 65476151	Classification Of Case:

Authentication Stamp
NP168

Wkw

SIGNATURE

PKS AUTOMOTIVE PTE LTD

7 TOH GUAN ROAD EAST, ALPHA INDUSTRIAL BUILDING #04-11 SINGAPORE 608599

Tel : 8614 6767 / 9182 6686 | Email : admin@pkautomotive.com

*not attached
all
d/s #2250
Hdy S.
Cheong A...*
23/2/21

ESTIMATION QUOTE

SOMPO INSURANCE SINGAPORE PTE LTD

VEHICLE NO : JMNS949
MAKE MODEL : HONDA/CIVIC
REFERENCE : PKS-202102-22
DOA : 3-Feb-21
CLAIM TYPE : Third Party Claim

ATTN : MOTOR CLAIMS DEPARTMENT

Page 1 of 2

LIST ITEMS	QTY	LIST PRICE (\$)	REMARKS
REAR BUMPER <i>fibre Dis ✓</i>	1	738	738 ✓
REAR BUMPER BRACKET <i>n1x</i>	2	47	47 X
REAR BUMPER RETAINER <i>ols one pc</i>	2	38	19 38 1PC
END PANEL <i>Dis ✓</i>	1	531	296 531 ✓
END PANEL TOP GANRISH <i>n1x</i>	1	160	108 160 ✓ x nn
REAR TAILLAMP LH <i>n1x</i>	1	326	326 X
REAR TAILLAMP RH <i>n20 ✓</i>	1	326	285.50 325 ✓
REAR EXHAUST SILENCER <i>n1x</i>	1	873	873 X
REAR EXHAUST MOUNTING <i>n1x</i>	2	40	40 X
BOOTLID <i>n1x</i>	1	710	710 X
BOOTLID WEATHERSTRIP <i>n1x</i>	1	115	115 X
BOOTLID EMBLEM LOGO <i>n1x</i>	1	45	45 X
BOOTLID EMBLEM-CIVIC <i>n1x</i>	1	39	39 X
BOOTLID EMBLEM - 1.8 <i>n1x</i>	1	32	32 X
BOOTLID EMBLEM 9 I VTEC <i>n1x</i>	1	45	45 X
BOOTLID LAMP LH <i>n1x</i>	1	245	245 X
BOOTLID LAMP RH <i>one ✓</i>	1	245	220.50 245 ✓
BOOTLID LOCK <i>n1x</i>	1	295	295 X
BOOTLID LOCK STRIKER <i>n1x</i>	1	55	55 X
BOOTLID HINGE <i>n1x</i>	2	110	110 X
BOOTLID INNER TRIM <i>n1x</i>	1	129	129 X
SPARE TYRE TOP BOARD <i>n1x</i>	1	297	297 X

5,441

LESS 20 % 1,088.2

SUBTOTAL 4,352.8

BALANCE C/F 4,352.8

SPECIAL NETT ITEMS	QTY	LIST PRICE (\$)	REMARKS
--------------------	-----	-----------------	---------

BALANCE B/F 4,352.8

REAR NUMBER PLATE <i>n1x</i>	1	80	80 X
REAR BUMPER CLIP <i>one ✓</i>	1 SET	30	30 ✓
BOOTLID INNER TRIM CLIP <i>n1x</i>	1 SET	20	20 X
REAR REVERSE SENSOR <i>broken n1x</i>	1 SET	400	400 X 200 (SN)

JOINT SEALANT	17	1	120	X	120
SUBTOTAL			650		
BALANCE C/F			<u>5,002.8</u>		

LABOUR		LIST PRICE (\$)	REMARKS
BALANCE B/F		5,002.8	
CHECK REAR WIRING AND LIGHTNING SYSTEM		80	80
REMOVE, REFIT REAR LINING, TRIM AND GANRISH		200	200
REMOVE AND RENEW REAR REVERSE SENSOR		120	120
REMOVE AND RENEW REAER EXHAUST		150	150
TRANSFER PARTS, ATTACHMENT FROM OLD BOOTLID TO NEW		200	200
PANEL BEATING AND RENEW DAMAGE PARTS ON AFFECTED AREAS		1,400	1,400
SPRAY PAINTING ON AFFECTED AREAS		1,500	1,500
APPLY ANTI RUST ON AFFECTED AREAS		120	120
SUBTOTAL		3,770	
GRAND TOTAL		<u>8,772.8</u>	

20
60
50
X
X
700
600
30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P- 1667
20%
P- 1333.60
S/N- 30.00
L- 1460
2823.60
20%
2258