

ASS. REC. BY:

REF: CS/CTI21002511/Ktf3

Special Instruction:

Surveyor: KENNETH

ASSIGNMENT (Office)

From (Person): LIONEL CHEW of CTI Date/Time: 23 February 2021 9:45 AM

Estimated Cost: Bill to:

OD ☒ IP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ 4154J Insured: YN 768Z

at Workshop m/s S Three Automotive Recovery Pte Ltd Tel: 9662 0282

of Blk 8 Sin Ming Industrial Estate #01-64/66

Policy No: Claim No: SNM21D201005

Sum Insured: Excess:

Make of Veh: D.O.A. 20.02.2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 23-02-21 3.41P.M. Person Contacted: YAN ZHEN Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SLZ 4154J- X
	YN 768Z- CS3/CTI21002368/R1vf3 DOA : 02/07/2020