



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO21002521/Uvf3q2	
			Date: 16/03/2021	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKZ 8282H	Veh. Inspected	SMP 9869M	
Policy No.	D20MTPV01007116	Coverage (\$)	0.00	
Claim No.	CMTD2100580/RUC	Excess (\$)	0.00	
Assign From	GRACE TEO	Assign Date	23/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN X-TRAIL (A)	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JN1JANT32Z0001957	Colour	BLACK	
Odometer	287192 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/55 R18	MICHELIN	6 mm	
L/H Front Tyre	235/55 R18	MICHELIN	6 mm	
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	20/02/2021	Inspection Date	23/02/2021	
Survey held at	TEAMWORK GARAGE PTE LTD 53 UBI AVENUE 1 #01-24 SINGAPORE 408934.			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	