

Submit to reference

159 TICK HAI MOTOR
1 KAKI BUKIT AVE 6 #01-20 SINGAPORE 417883
TEL: 6842 9089 FAX: 6841 2869
REG NO : 53033608A

Vehicle Number: SCW6266D
Vehicle Model : Toyota Wish 1.8A
Manufacturing Year: 2009
Chassis : JTDER12W103001904

Not Authorized
date
23/2/21
8 days
2/5 @ 8300/
the price after repair.

S/N.	Item Description	Amount (\$)
1	Front Bonnet R	\$ 753.89
2	Front Bonnet Chrome CNG	\$ 254.43
3	Front Bonnet Under Rubber Seal 11	\$ 161.75
4	Front Bonnet Undercover Clip x 1 set 11	\$ 50.00
5	Front Bonnet Lock 11	\$ 141.40
6	Front Bonnet Hinge x 2 pcs 11	\$ 174.80
7	Toyota Centre Logo 11	\$ 85.00
8	Headlamp x 2 pcs 670.10 x 2 = 1340.20 CNG	\$ 1,407.40
9	Front Bumper 498.10 DD/OE	\$ 1,077.00
10	Front Bumper Side Retainer x 2 pcs 11	\$ 179.00
11	Front Bumper Reinforcement 366.10 DD	\$ 385.10
12	Front Bumper Sponge Torn	\$ 131.20
13	Front Bumper Clip x 1 set 11	\$ 50.00
14	Front Bumper Lower Grille Torn	\$ 125.60
15	Foglamp Cover x 2 pcs 11	\$ 103.44
16	Front Grille CNG	\$ 161.80
17	Front Fender (LH) R	\$ 757.90
18	Front Support Panel R	\$ 881.25
19	Front Support Panel Top Garnish 11	\$ 125.40
20	Radiator 811	\$ 702.24
21	Radiator Lower Undercover Torn	\$ 128.54
22	Air Con Condenser 311	\$ 624.36
23	Horn x 2 pcs 11	\$ 128.40
24	Rear Bumper 485.10 Dis	\$ 1,246.28
25	Rear Bumper Side Retainer x 2 pcs 66.50 O/S Bent	\$ 207.60
26	Rear Bumper Reflector (RH) 310	\$ 89.15
27	Rear Bumper Clip x 1 set 11	\$ 50.00
28	Rear Bumper bracket (RH) 10	\$ 90.95
29	Taillamp x 2 pcs 408.10 O/S CNG	\$ 1,249.30
30	Taillamp Lower Retainer (RH) 65.00 CNG	\$ 77.32
31	Air Duct (RH) 215	\$ 85.40
32	Taillamp Lower Panel (RH) 488.20 Buck/worped	\$ 568.20
33	Rear Fender - inner Garnish (RH) 145.80 Del/Torn	\$ 276.10

X
/
X
X
X
X
X
/
/
/
/
/
/
/
/
/
/
/
/
/
/
/
/
/
/

8654.53

To straighten, repair, realign on affected area and replace damaged parts	\$ 2,500.00
To spray painting on affected area	\$ 1,800.00
Labour Total :	\$ 5,710.00
Total (Parts & Labour)	\$ 20,744.79

1100
1500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-697877
S/N-290-00
L-3210

1047887
8387