



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN: YU Dominic Yishan			Ref: CC4/ASM21002535/Apa3q2 Date: 17/05/2021 Code: ASM	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 1615J	Veh. Inspected	SVJ 2563U	
Policy No.	VFX/P2419138	Coverage (\$)	0.00	
Claim No.	S1M035GS	Excess (\$)	0.00	
Assign From		Assign Date	23/02/2021	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	TOYOTA WISH	c.c	1987	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JTDGJ20W905001825	Colour	RED	
Odometer	184125 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	MICHELIN	6 mm	
L/H Front Tyre	195/65 R15	MICHELIN	6 mm	
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	22/02/2021	Inspection Date	23/02/2021	
Survey held at	FONG MOTORS 1 KAKI BUKIT AVE 6 #01-27/01-45 SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	