

ASS. REC. BY: Tom

REF: CC3/AIG 2100 2544/RH/B

9200

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SMW 48032  
 at Workshop m/s PREMIUM  
 of BENSON STATION  
 Insured: ALH  
 Policy No. 2070161915  
 Claims No. 2603346910SG  
 Sum Insured: \_\_\_\_\_ Excess: TBA 800  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its  
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 142K  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA /  REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: SMW 48032 Yr Regn: 2020/ NOV  
 Type:  M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Audi Q3 1.4 TFSI S.T c.c. 1395  
 Colour: Red A/C: Insured / Std / NI / NA  
 Sp. Reading: 3611 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WAUZZZF33M1014796  
 Gen. Cond: Good /  Fair / Poor / Burnt  
 Steering:  order / Jammed / Leaked / Burnt or  
 Brake:  order / Jammed / Leaked / Burnt or  
 Mod: Nil /  SRim / STD A/Rim or  
 Tyre Size: F: 215/65R17  
 R: 21  
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or: CONTINENTAL  
 Front R/Bal. 6 mm Rear R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 20/02/2021 D.O.I. 23/02/21  
 Survey held at PREMIUM  
 Des. of Damages:  Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair List - 78K</u>
	<u>confirm repair cost of \$18,503.84 @ 9 days</u>
	<u>red: 22808.16; 55%</u>

Date/Time, File Pass to?  : Prel. Report  : Final Report

1) \_\_\_\_\_ Date/Time, File Return to? \_\_\_\_\_

2) \_\_\_\_\_

Report Format: \_\_\_\_\_

Lump Sum / I.S.F. (%) \_\_\_\_\_

Days Of Repair: 9

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

\$ + RS. \$ \_\_\_\_\_

Photos \_\_\_\_\_

Others \_\_\_\_\_

TOTAL \_\_\_\_\_

Add Fee:  : Site Insp (\$) \_\_\_\_\_

: Interview (\$) \_\_\_\_\_

: Tech. Invs (\$) \_\_\_\_\_

: Weekend (\$) \_\_\_\_\_