

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 08 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: G 47818 Yr Regn: 09, 16Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Mercedes C.C. 1498Colour: M. Green Insured / Std / NI / NASp. Reading: 43720 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6DJ2HAA01700843Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD / Rlm orTyre Size: F: 105/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 23/2/21 D.O.I. 24/2/2021

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1) EST NOT ready, may repair at I.B.I as no 2nd parts available

Date/Time, File Pass to?

☐ : Prell. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 749F

Vehicle Details

Vehicle No.: SLG4781Z
Vehicle to be Exported: No
Intended Deregistration Date: 23 Feb 2021
Vehicle Make: MAZDA
Vehicle Model: MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour: Pink
Manufacturing Year: 2016
Engine No.: P520356776
Chassis No.: JM6DJ2HAA01100843
Maximum Power Output: 85.0 kW (113 bhp)
Open Market Value: \$17,204.00
Original Registration Date: 30 Sep 2016
First Registration Date: 30 Sep 2016
Transfer Count: 0
Actual ARF Paid: \$7,204.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 29 Sep 2026
PARF Rebate Amount: \$5,403.00

Intended COE Rebate Details

COE Expiry Date: 29 Sep 2026
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$50,000.00
COE Rebate Amount: \$28,000.00
Total Rebate Amount: \$33,403.00

The information contained herein is correct as at 23 Feb 2021

OK



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	23/02/2021 16:29 (SGT)
Date of Accident	23/02/2021 07:30 (SGT)
Exact Location of Accident	Hougang Ave 2, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG4781Z
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LEE HUI LING
NRIC No	SXXXX749F
Email Address	HUDDINGTON@YAHOO.COM
Mobile Phone No	(Phone) +65-97887687
Alternative Phone No	+65-97887687

VEHICLE PARTICULARS

Manufacturer	Mazda
Model	2
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	Direct Asia
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MT/00832833
Cover Note Number	30/09/2020 - 29/09/2021

DRIVER

Name of Driver	LEE HUI LING
NRIC No	SXXXX749F
Date Of Birth	31/03/1964
Occupation	Indoor



Date Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

09/06/1993
27 YEARS AND 8 MONTHS
Female
(Phone) +65-97887687
+65-97887687
HUDDINGTON@YAHOO.COM
53 HUDDINGTON AVE

-
557623
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

PLS REFER TO THE SKETCH PLAN BY DRIVER

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? Yes
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLP5081G
Vehicle Manufacturer -
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver EMELINE CHOO POR HUAY
NRIC No SXXXX607D
Contact Number -
Address -
Address complement -
Postcode -


Date of accident: 23 Feb 2021 Time: 1:30 PM Location: Hougang Ave 2
My Vehicle A: SLG 47817

Time: 1300 hrs Location:

Location: Hougans Ave 2

Vehicle B: SLP 20816

Vehicle C:



I was driving along Honggang Ave 2, the car in front suddenly stopped, I pressed brake, but I think the car behind was not alert and hit my car.

Remarks : Please forward a copy of my efile accident report to :

My workshop :

Email address :

& myself :

Email address :

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under you own policy. Kindly check with your own insurer for more information.

I/We declare the foregoing particulars are true in every respect.

... thinking

