


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLU 7215Z
 at Workshop m/s TAN CHONG MOTOR
 of 911, BUKIT TIMAH RD
 Insured: LPC
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLU 7215Z Yr Regn: 2017, DLK
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: NISSAN QASHQAI 1.2015 c.c 1197
 Colour: Bronze A/C: Insured / Std / NI / NA
 Sp. Reading: 5604 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: SJN FGA 511U2119610
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: NI / SRim / STD A/Rim or _____
 Tyre Size: F: 225/40R19
 R: 20
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 72K
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 23/02/21 D.O.I. 02/03/21
 Survey held at TAN CHONG
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair cost = 28K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____ \$ + RS. _____ SI
 Photos _____
 Others _____
 TOTAL _____

1) _____
 2) _____

Report Format: _____
 Lump Sum / I.S.A. (%) _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

TAN CHONG MOTOR SALES PTE. LTD.
511, BUKIT TIMAH ROAD
SINGAPORE 589623

1.55

24/02/2021

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : BUKIT TIMAH
CONTACT NO : 4694091
REFERENCE : INS/IC/LAW/0055/2021
DATE : 24-FEB-2021

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : MR LIM CHENG HAN
ADDRESS : BLK 291C BUKIT BATOK STREET 24
#18-27
S(652291)
TELEPHONE NO : 65657215/97858741

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : TP-GBF3903U
VEHICLE NO : SLU7215Z
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2531456A
CHASSIS NO : SJNFEAJ11U2119610
MILEAGE : 1 KM
DATE IN : 24/02/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : LAWRENCE
ACCIDENT DATE : 23/02/2021

DIRECT SETTLEMENT
OWNER CLAIMING LOSS OF USE / RENTAL
CAR AT WORKSHOP / CAR NOT AT WORKSHOP
KINDLY REVERT TO ME ASAP
EMAIL : lawrenceteo@tanchong.com
H/P : 94568832 FAX : 64697472

Ar
Law
10/21

TAN CHONG MOTOR SALES PTE. LTD.

BUKIT TIMAH W/SHOP

SERVICE DEPARTMENT

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	RITCAM	REMOVE/INSTALL & TEST REAR REVERSE CAMERA	120.00	/
2	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL \$120/PANEL X 03	360.00	120
3	RS	SUPPLY & INSTALL REVERSE SENSOR	110.00	/
4	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA \$100/PANEL X 03	300.00	100
5	SRW	INSTALL ULTRAMAX SOLAR FILM - REAR W/SCREEN	150.00	/
6	UG14	RENEW REAR WINDSCREEN GLASS ASSY.	240.00	760
7	ZZ/001	REPAIR LH/RH REAR FENDER AND RENEW TAILGATE, REAR BUMPER AND END PANEL	1500.00	780
8	ZZ/002	S/PAINT REAR PORTION	1500.00	600
9	ZZ/003	CHECK LIGHTING	48.00	/
10	ZZ/004	TRANSFER TAILGATE MECHNICAL PARTS	80.00	/
11	ZZ/005	R/I REAR DVR TO ASSIST REPAIR	120.00	/
TOTAL LABOUR CHARGES			4528.00	

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 EMBLEM <i>ne /</i>	90892-4EA0A	94.40		
2 EMBLEM-REAR <i>ne /</i>	90890-4EA0A	64.90		
3 STRIKER-TAIL GA <i>?</i>	90570-4EA0A	34.80		
4 A LOCK LIFT <i>?</i>	90502-4EA1B	173.20		
5 WEATHER STRIP <i>?</i>	90830-4EA0B	167.00		
6 A FIN BACK DOOR TOP NO PLATE <i>de /</i>	90810-4ES0H	352.00		
7 RUBBER-DUM <i>ne /</i>	G2716-89900	63.80		
8 GLASS-TAIL GATE <i>ne / photo</i>	90300-HV00A	990.00		
9 DOOR BACK <i>bf /</i>	K0100-HV0MB	3062.60		
10 GROMMET BUMPER \$2.40 EA X 02 <i>ne /</i>	01281-00111			4.80
11 GROMMET BUMPER \$2.70 EA X 04 <i>ne /</i>	63846-5V000	10.80		
12 CLIP BUMPER \$8.00 EA X 03 <i>ne /</i>	85284-JD00A	24.00		
13 CANOE RIVET BUMPER \$7.10 EA X 02 <i>ne /</i>	76882-0M000	14.20		
14 RETAINER-BUMPER RH <i>?</i>	79184-4EA0A	25.70		
15 RETAINER-BUMPER LH <i>?</i>	79185-4EA0A	25.70		
16 BRACKET-BUMPER RH <i>?</i>	85220-4EA0A	38.90		
17 BRACKET-BUMPER LH <i>?</i>	85221-4EA0A	38.90		
18 STAY ASSY-REAR RH <i>?</i>	H5210-4EAMA	141.00		
19 STAY ASSY-REAR LH <i>?</i>	H5211-4EAMA	141.00		
20 REINF-BUMPER RR <i>?</i>	H5030-4EAMA	691.50		
21 ENERGY ABSORBER <i>?</i>	85090-HV00A	141.40		
22 FASCIA-RR BUMP <i>de /</i>	85022-HV00H	796.70		
23 CLIP FINISHER END PANEL \$1.30 EA X 04 <i>ne / ?</i>	01554-00181	5.20		
24 CLIP END PANEL \$1.30 EA X 02 <i>?</i>	01553-05323	2.60		
25 PLATE-LUGGAGE <i>?</i>	84992-4EA0A	68.80		

TAN CHONG MOTOR SALES PTE. LTD.
 BUKIT TIMAH W/SHOP
 SERVICE DEPARTMENT

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLU7215Z

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 PANEL-REAR UPPE ?	G9110-HV0MA	482.60		
27 CLIP FENDER ARC/BUMPER \$1.30 EA X 04 <i>ne</i>	01553-05933	5.20		
28 FENDER RH REAR ARC ?	93828-4EA0A	540.50		
29 FENDER ARC LH REAR ?	93829-4EA0A	540.50		
30 MOTOR-WIPER ?	28710-4EL0A			427.30
31 GROMMET C/LAMP \$27.90 EA X 02 <i>ne</i>	76848-83P00	55.80		
32 GROMMET C/LAMP \$2.00 EA X 02 <i>ne</i>	76848-35F00	4.00		
33 CLIP C/LAMP \$5.40 EA X 02 <i>ne</i>	26398-ED000	10.80		
34 LAMP COMB RR,LH BOOT ?	26555-HV55A	231.30		
35 LAMP COMB RR,LH ?	26555-HV00A	346.90		
36 CLIP GRILLE RAD \$1.80 EA X 04 <i>Xid consyht</i>	01515-00QAB	7.20		
37 GRILLE-RADIATOR <i>X mconsyht</i>	62310-HV00A	486.00		
38 CAMERA BRACKET <i>ne</i>	BRACKET-CAM			20.00
39 SUNDRIES <i>ne</i>	NPN			100.00
40 REAR W/SCREEN SEALANT <i>m</i>	SEALANT - 4			80.00
41 SENSOR-REVERSE <i>se</i>	SENSOR			250.00
SUB TOTAL		9879.90	0.00	882.10
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1975.98	0.00	0.00
GRAND TOTAL		7903.92	0.00	882.10
OVERALL TOTAL		8786.02		

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

TAN CHONG MOTOR SALES PTE. LTD.
BUKIT TIMAH W/SHOP
SERVICE DEPARTMENT

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLU7215Z

TOTAL LABOUR CHARGES	4528.00
TOTAL SPARE PARTS CHARGES	8786.02
GRAND TOTAL	13314.02 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - Hp 90010068
SURVEYED DATE	:	02/03/21 @ 1000 hrs
AUTHORIZED DATE	:	4 days
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	Resy before part

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date Of Driving Pass	03/03/1986
Driving experience	34 YEARS AND 11 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97858741
Alt. Phone Number	+65-97858741
Email Address	cheng.han.lim@udtrucks.com
Address	291C BUKIT BATOK STREET 24 #18-27
Address complement	-
Postcode	652291
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Bukit Batok Neighbourhood Police Centre
Police Station Phone No	(Phone) +65-18006659999
Alt. Police Station Phone No	(Fax) +65-64252661
Police Station Address	21 Bukit Batok East Ave 4 Singapore 659840
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

SEE ATTACHED.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF3903U
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	ZHENG DE JIAN
Contact Number	(Phone) +65-82136666

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	LIM CHENG HAN
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BACK , STIFF NECK AND HEAD
Injured person in which vehicle?	SLU7215Z
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

Vehicle No: _____

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurer and/or companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time: _____

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: _____

Reporting Centre's Name: _____
 Name: _____
 NRIC/ID No: _____

Copyright © 2008 by GIA



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(A) My Vehicle No: SLU 7215 Z

Accident Location: PIE to Tuas near Exit 41

Accident Date: 23.02.2021 Time: 0841 am/pm

- Brief Details of Accident -

As I was driving to work at PIE toward Tuas near Exit 41 slowing down traffic on lane 4, suddenly GBF 3903U without slowing down bang hard onto my rear causes damage.

- Other Vehicle Involve Details -

(B) Veh No: GBF 3903U Hp: B2136666 Pax: Driver Name: Zheng De Jian
 (C) Veh No: Hp: Pax: Driver Name:

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Officer's Signature
 Name:
 NRIC/FIN No:

SIATIC SKETCH PLAN #001_V3



Police Station Of Origin
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No. 1800-6659999

1 of 3

Report No. 1/20210225/2077

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made 25/02/2021 17:30	Video Report No.	Station Diary No. 88
---	------------------	-------------------------

Informant's Particulars

Name of Informant LIM CHENG HAN		Address: APT BLK 291C BUKIT BATOK STREET 24 #18-27 SINGAPORE 652291	
ID Type / ID No. NRIC NO / S1804287H		Contact No. Home/Office:	Mobile: 97858741
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 53	Date of Birth: 24/09/1967	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: DRIVER DEVELOPMENT EXECUTIVE		Driving Licence Information: Class: 3,4,5	Date of Expiry:

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive No	Date/Time of Accident: 23/02/2021 08:40	Type of Location: Straight Road
Location: PAN-ISLAND EXPRESSWAY				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

Details of Vehicle Involved

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBF3903U	Lorry	TOYOTA	DYNA	Silver		0
SLU7215Z	Car	NISSAN	QASHQAI 1.2 DIG-T CVT	Brown	Seriously Damaged	0

Details of Vehicle Insurance

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



Police Station Of Origin
Bukit Batok N.P.C
21 Bukit Batok East Avenue 4 SINGAPORE
659840
Tel No 1800-6659999

2 of 2
Report No. 1/2021022502077

CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SLU7215Z	AIG ASIA PACIFIC INSURANCE PTE. LTD.	1700088445-03	12/12/2020	11/12/2021

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL			Use of Pedestrian Crossing: NA	
Driver				
Name	ZHENG DEJIAN	ID No	S2744902F	
Related Vehicle	GBF3903U (Lorry)	Contact No	82136666	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	
Driver				
Name	LIM CHENG HAN	ID No.	S1804287H	
Related Vehicle	SLU7215Z (Car)	Contact No.	97858741	
Hospital/Clinic	MY FAMILY CLINIC (PIONEER)	Class of Driving Licence & Expiry Date	Class: 3 4 5 Date of Expiry: NIL	
Date Treatment	25/02/2021	Date Discharge	25/02/2021	
No. of Days granted Medical Leave	03	Degree of Injury	NIL	

Brief Details.

On 23/02/2021 at 0841hrs, I was driving my car, SLU7215Z along PIE towards Tuas. Then near exit 41 I was driving along lane 4 and the vehicles in front of me were slowing down. I started slowing down and a while later a lorry, GBF3903U, which did not slow down, collided onto the rear portion of my car. No traffic police or ambulance were at the accident scene. My car is equipped with in-car camera and I have the footage of the accident. I had also seen a doctor as I felt pain on my back, stiffness of the neck and head.

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : _____ Vehicle Registration No: SLW 7215 Z
 Name (as shown in NRIC): LIM CHENG HAN NRIC/FIN/Passport No: S1804257/H
 (*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
 Address: BK 291C DST BATAK ST 24 #18-27 Singapore 652910
 Contact (Tel): 97358741 Mobile No: _____
 Email Address: cheng han lim@votricks.com
 Date of Accident: 23.02.2021 Time of Accident: 08.41 am
 Place of Accident: DVE toward Tuas ^{near} Exit 41
 Insurance Company: AIC

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

SEE ATTACHED POLICE REPORT

[Signature]
 Policyholder / Driver's Signature
 Date: _____

[Signature]
 Reporting Centre Personnel's Signature
 Name: _____
 NRIC/FIN No.: _____
 Date: 26/02/2021

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	287H
Vehicle No.:	SLU7215Z
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2021
Vehicle Make:	NISSAN
Vehicle Model:	QASHQAI 1.2 DIG-T CVT
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	HRA2531456A
Chassis No.:	SJNFEAJ11U211961Q
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$20,143.00
Original Registration Date:	12 Dec 2017
First Registration Date:	12 Dec 2017
Transfer Count:	0
Actual ARF Paid:	\$15,201.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Dec 2027
PARF Rebate Amount:	\$11,400.00
COE Expiry Date:	11 Dec 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$47,112.00
COE Rebate Amount:	\$31,901.00
Total Rebate Amount:	\$43,301.00

The information contained herein is correct as at 03 Mar 2021

OK



► Nissan Qashqai 1.2A DIG-T

- Overview**
- Financial
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$72,777		
Depreciation ⓘ	\$9,600 /yr View models with similar depre	Reg Date	15-Dec-2017 (6yrs 9mths 11days COE left)
Mileage	45,000 km (14k /yr)	Manufactured ⓘ	2017
Road Tax ⓘ	\$508 /yr	Transmission	Auto
Dereg Value ⓘ	\$39,741 as of today (change)	OMV ⓘ	\$20,143
COE ⓘ	\$41,761	ARF ⓘ	\$15,201
Engine Cap	1,197 cc	Power	85.0 kW (113 bhp)
Curb Weight ⓘ	1,325 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		

Features

1.2L Turbocharged DOHC Engine With 7 Speed XTronic CVT Transmission, 2WD, Keyless System, Traction Control. [View Specs Of The Nissan Qashqai \(2014-202\)](#) [View specs of the Nissan Qashqai \(2014-2020\)](#)

Accessories

Sports Rims, Leather Seats, Factory Fitted Audio With Bluetooth, Steering Controls, Reverse Camera, Sensors

Compare ⓘ
 Fa... owner. Excellent Fuel Efficiency At 17.9/L Smooth And Quiet Engine. Road Tax Till Dec 2021.

