

ASS. REC. BY:

REF: CS3/ASM21002576/Qvf3

Special Instruction:

Surveyor: SUN PINASSIGNMENT (Office)From (Person): TAN JUN HONG of AXA Date/Time: 24/2/2021 11:36 AM

Estimated Cost: _____ Bill to: _____

OD: ☒ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJD 2858P Insured: SHD 6968Cat Workshop m/s E M SOLUTION PTE LTD Tel: 64560226of 160 Sin Ming Drive Auto City, #03-18, 575722 Sin MingPolicy No: _____ Claim No: S1M033SI

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 22-02-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 24-02-21 4.21P.MPerson Contacted: BERNARD Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SJD 2858P- CV1/VAL15019667/Cv DOA :16/11/2015
	SHD 6968C- CS/FCI19009599/Etd3e2 DOA :23/05/2019