

China (PIP)

COMFORTDELGRO ENGINEERING PTE LTD  
REPAIR ESTIMATE

Date: 17.02.2021  
Time: 10:36:55  
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305454142  
REGN NO : SH 7883E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 17.02.2021 09:00  
ACCIDENT DATE : 08.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

|                                                 |      |          |       |          |       |
|-------------------------------------------------|------|----------|-------|----------|-------|
| 0001 04-01-0104-2282-G COVER-RR BUMPER#         | 1    | 459.40   | 20.00 | 367.52   | ✓ LK  |
| 0002 04-01-0104-0575-G PANEL ASSY-QUARTER OUTER | 1    | 1,768.30 | 20.00 | 1,414.64 | ✓ LYT |
| 0003 04-01-0104-1150-A PROTECTOR MAT            | 1 N  | 50.00    | 2.00- | 50.00    | ✓ NEL |
| 0004 04-01-0101-0111-G BUMPER COVER CLIP REAR   | 10 L | 22.00    | 20.00 | 17.60    | XJVL  |
| 0005 03-01-0104-2137-G CAP ASSY-WHEEL HUB       | 1    | 346.40   | 20.00 | 277.12   | ✓ SCR |

SUB-TOTAL : 2,126.88

JOB NATURE

|             |                              |         |         |
|-------------|------------------------------|---------|---------|
| 0000 PB     | PANEL BEATING                | 1200.00 | 700     |
| 0001 SP     | SPRAYPAINT CHARGE            | 600.00  | 400 500 |
| 0002 17-01  | CHECK ALL LIGHTING           | 50.00   | 20      |
| 0003 20-00  | TUFF COAT ON AFFECTED PARTS. | 50.00   | 30      |
| 0004 20-204 | REMOVE/REFIX UPHOLSTERY REAR | 120.00  | XNAJ 80 |
| 0005 L      | REMOVE/REFIX REVERSE SENSOR  | 80.00   | 30      |

NAZ LK  
17/2/2021 1530

PIP  
3 Days

BEFORE PAINT PHOTOS

Liwa Auto Cons. must be notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## COMFORTDELGRO ENGINEERING PTE LTD

Date: 17.02.2021

Time: 10:36:55

## REPAIR ESTIMATE

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010045  
ADDRESS : COMFORT TRANSPORTATION PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65508755

JOB NO : 305454142  
REGN NO : SH 7883E  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 22.10.2019  
DATE/TIME IN : 17.02.2021 09:0  
ACCIDENT DATE : 08.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

SUB-TOTAL : 2,100.00

TOTAL : 4,226.88

MVA NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO  
SURVEYOR NAME & SIGNATURE  
DATE :

Page : 1

JC NO.: 305454142

**JOB CARD** Sales Order:

REGN NO.: **SH 7883E**

MILEAGE

MAKE : **HYUNDAI**

FUEL

MODEL IONIQ(G3).

DATE/TIME IN  
17.02.2021 09:00

YR OF MANU. 22.10.2019


TARGET DATE

CHASSIS CODE  
KMHC851CVLU186499

COMPLETION DATE/TIME:

### JOB DESCRIPTION

| 1/NO | LABOR CODE | DESCRIPTION |
|------|------------|-------------|
|------|------------|-------------|



## SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Exit Pass

No. SH 7883E JU CHINA LKK

Vehicle No.: **SH 7883E**

f Service Advisor

Signature/Date

Name of Service Advisor

Date \_\_\_\_\_

turned to Service Reception upon collection

To be kept by Security Guard