

ASS. REC. BY:

Form
PRS

REF:

CS3/AH 21002581 R1v f3

7782

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 7829P

at Workshop m/s THIAM HENG

of 7A, JLN PAPAN

Insured: AH

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 58K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBH 7829P Yr Regn: 2018 SEP

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: NISSAN NV 350 P.V 2.5 SMT c.c 2488

Colour: GRY A/C: Insured / Std / NI / NA

Sp. Reading: 55267 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JWMC2E2620009157

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Order / Jammed / Leaked / Burnt or _____

Brake: Order / Jammed / Leaked / Burnt or _____

Mod: NI / R/Rim / STD A/Rim or _____

Tyre Size: F: RXRISC

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or GREEN-MAX

Front Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 22/02/21 D.O.I. 26/02/21

Survey held at THIAM HENG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

The U/C / Chassis frame / Body Structure affected due to collision.

| Date / Time | Action / Instruction |
|-------------|-------------------------|
| | <u>Report Int - 37K</u> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Prell. Report : Final Report

Days Of Repair: 4
Resurvey No. of Trip: _____

Date/Time, File Return to? 5/3/21-Typist

Add Fee: : Site Insp (\$) : Interview (\$) : Tech, Invs (\$) : Weekend (\$)

| | |
|-----------------|--|
| Survey Fee: | |
| Transportation: | |
| Photos | |
| Others | |
| TOTAL | |

Rep. Format: DAR
Lump Sum / I.B.F. (\$) _____

(1)Distorted (2)Cracked (3)Cut (4)Scratched
 (5)Bent (6)Shifted (7)Buckled (8)Broken (9)Necessary
 (10)Tom (11)Unconfirmed (12)Not Working

VAN / LORRY (Rear)

GBH 7829 P

ACTION (AC)
 (1)Replace (✓) (2)Repair (X) (3)Check (?)
 (4)Not Consistent (NC)

Aug 2/95

Vehicle No:

| INC | Item | CON | AC | Qty |
|--------|-----------------------------|-----|----|-----|
| 993626 | Rear Number Plate | | | |
| 993627 | Rear Number Plate Base | | | |
| 993628 | Rear Number Plate Bracket | | | |
| 993632 | Rear Number Plate Lamp | | | |
| 992958 | Rear Bumper | | | |
| 993108 | Rear Bumper Upper | | | |
| 993017 | Rear Bumper Lower | | | |
| 993054 | Rear Bumper Side | | | |
| 992976 | Rear Bumper Bracket | | | |
| 993068 | Rear Bumper Side Retainer | | | |
| 993045 | Rear Bumper Reinforcement | | | |
| 993081 | Rear Bumper Step Panel | | | |
| 993079 | Rear Bumper Step Garnish | | | |
| 993186 | Rear Crash Bar | | | |
| 994023 | Reverse Sensor | | | |
| 993327 | Rear End Panel | | | |
| 993851 | Rear LH Taillamp | SUL | / | |
| 993853 | Rear LH Taillamp Garnish | | | |
| 993859 | Rear LH Taillamp Panel | | | |
| 995116 | Rear RH Taillamp | | | |
| 993853 | Rear RH Taillamp Garnish | | | |
| 993859 | Rear RH Taillamp Panel | | | |
| 993554 | Rear Apron Panel | | | |
| 995156 | Rear LH Door | | | |
| 993201 | Rear RH Door | | | |
| 991328 | Rear Door Emblem | | | |
| 993274 | Rear Door Outer Handle | | | |
| 993228 | Rear Door Garnish | | | |
| 993294 | Rear Door Rubber | | | |
| 995194 | Rear LH Door Hinge | | | |
| 995307 | Rear RH Door Hinge | | | |
| 993261 | Rear LH Door Lock | | | |
| 993261 | Rear RH Door Lock | | | |
| 993232 | Rear Door Glass | | | |
| 993955 | Rear Door Glass Sealant | | | |
| 994729 | Third Brake Light | | | |
| 994543 | Tailgate | | | |
| 993700 | Rear Rubber Stopper | | | |
| 993701 | Rear Rubber Stopper Bracket | | | |
| 991328 | Tailgate Emblem | | | |
| 994643 | Tailgate Outer Handle | | | |
| 994545 | Tailgate Garnish | | | |
| 994602 | Tailgate Glass | | | |
| 994606 | Tailgate Glass Rubber | | | |
| 994604 | Tailgate Glass Moulding | | | |
| 994607 | Tailgate Glass Sealant | | | |
| 994597 | Tailgate Extension Mirror | | | |
| 994629 | Tailgate Lock | | | |
| 994651 | Tailgate Rubber | | | |
| 994611 | Tailgate Hinge | | | |
| 994594 | Tailgate Damper | | | |
| 994613 | Tailgate Inner Board | | | |
| 993992 | Rear Wiper Arm | | | |
| 993995 | Rear Wiper Blade | | | |
| 993997 | Rear Wiper Motor | | | |
| 993484 | Rear Floor Panel | | | |
| 995065 | Spare Tyre | | | |
| 993785 | Spare Tyre Bracket | | | |
| 993364 | Rear Exhaust Pipe | | | |
| 993361 | Rear Exhaust Mounting | | | |
| 995223 | Rear LH Chassis Member | | | |
| 993165 | Rear RH Chassis Member | | | |

| NAC | INC | Item | CON | AC | Qty |
|--------|--------------------------------|------|-----|----|-----|
| 993748 | Rear Sidegate | | | | |
| 994225 | Rear Sidegate Lock | | | | |
| 993749 | Rear Sidegate Hinge | | | | |
| 994226 | Sidegate Lower Panel | | | | |
| 994227 | Sidegate Railing | | | | |
| 994208 | Side Cover Hook | | | | |
| 991965 | Side Step Panel | | | | |
| 994496 | Side Step Panel Stopper | | | | |
| 992857 | Rear Body Panel | | | | |
| 992866 | Rear Body Panel Inner | | | | |
| 995329 | Sliding Door LH | BT | / | | |
| 995328 | Sliding Door RH | | | | |
| 994295 | Sliding Door Handle | | | | |
| 994300 | Sliding Door Lock | | | | |
| 994313 | Sliding Door Rubber | | | | |
| 994291 | Sliding Door Bottom Roller | | | | |
| 994317 | Sliding Door Top Roller | | | | |
| 994306 | Sliding Door Rail | | | | |
| 994315 | Sliding Door Stepboard | | | | |
| 994316 | Sliding Door Stepboard Garnish | | | | |
| 993621 | Rear LH Mudflap | | | | |
| 993933 | Rear LH Wheel Rim | | | | |
| 994025 | Rear LH Rim Cover | SUL | / | | |
| 995065 | Rear LH Tyre | | | | |
| 993622 | Rear RH Mudflap | | | | |
| 993934 | Rear RH Wheel Rim | | | | |
| 994025 | Rear RH Rim Cover | | | | |
| 995065 | Rear RH Tyre | | | | |
| 992179 | Fuel Tank | | | | |
| 992184 | Fuel Tank Bracket | | | | |
| 990247 | Sticker | | | | |
| | LH SIDE PILLAR (outer) | SUL | R | | |
| | REAR LH SIDE PANEL | SUL | R | | |

4 days