

FASTECH AUTO PTE LTD
 BLK 1 KAKI BUKIT AVE 6
 #01-46/48/50 AUTOBAY
 SINGAPORE 417883

Alle certie

no of Author
 name

24/2/21

2/5 @ 3500

take photo this car

4 days

VEHICLE No: SKQ 6623T

1PC REAR WINDSCREEN MOULDING
 1PC TAILGATE
 1PC TAILGATE REAR LOGO
 1PC TAILGATE 'FORESTER' EMBLEM
 1PC TAILGATE 'SUBARU' EMBLEM
 1PC TAILGATE 'AWA' EMBLEM
 1PC TAILGATE INNER LOCK
 1PC TAILGATE INNER TRIM BOARD
 1SET TAILGATE INNER TRIM BOARD CLIPS
 1PC TAILGATE WEATHERSTRIP
 1PC REAR BUMPER
 1SET REAR BUMPER CLIPS
 1PC REAR BUMPER TOW COVER
 2PCS REAR BUMPER REFLECTORS @\$65.00
 1PC REAR BUMPER REINFORCEMENT
 2PCS REAR BUMPER SIDE RETAINERS @\$60.00
 1PC REAR BUMPER LOWER SKIRTING
 1PC REAR END PANEL
 1PC REAR END PANEL TOP GARNISH
 2PCS TAILLAMPS @\$1180.00
 1PC REAR EXHAUST
 1PC REAR EXHAUST MOUNTING
 1PC REAR FLOOR PANEL
 1PC REAR FLOOR PANEL TOP BOARD

55
 52
 50

722.30
 48.00

365.20

485.20

182.40

650.00

2843.1
 282
 2274.48

11 \$122.00 X
 R \$2,250.00 X
 11 \$105.00 X
 net \$89.00 /
 net \$92.00 /
 net \$65.00 /
 11 \$245.00 X
 11 \$566.20 X
 11 \$50.00 X
 twi \$168.00 /
 00 \$1,200.00 /
 net \$60.00 /
 R \$38.00 X
 nscen \$130.00 IPC
 Bent \$615.00 /
 11 \$120.00 X
 NT \$1,100.00 X
 00 \$845.00 /
 twi \$199.00 /
 nscen \$2,360.00 IPC
 11 \$845.00 X
 11 \$56.00 X
 11 \$1,145.00 X
 11 \$650.00 X
 \$13,115.20

20h

S.NETT
 1PC REAR WINDSCREEN SEALANT
 1PC REAR WINDSCREEN INNER SEAL
 1SET REAR BUMPER REVERSE SENSOR
 1PC REAR END PANEL SEALANT
 1SET REAR FLOOR PANEL INSULATOR

11 \$50.00 X
 11 \$50.00 X
 should \$280.00 200
 net \$50.00 /
 11 \$200.00 X

TO CHECK WIRING
 TO DISMANTLE & REPLACED REVERSE SENSOR
 TO DISMANTLE & REFIX REAR WINDSCREEN
 TO DISMANTLE & REFIX CUSHION UPHOLSTERY
 TO DISMANTLE & REFIX REAR EXHAUST
 TO TRANSFER TAILGATE MECHANISM
 TO SPRAY RUST PROOFING
 LABOUR FOR PANEL BEATING & REPLACED PARTS

\$50 30
 \$80.00 50
 11 \$150.00 X
 \$100.00 80
 11 \$100.00 X
 11 \$100.00 X
 \$150 30
 \$1,800.00 800

TO PUTTY & SPRAT PAINTING

TOTAL \$1,800.00 900
\$18,075.20

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please read carefully the details of the accident covered by this form.
2. This form must be completed by the Police Officer or the LKK Auto Consultant.
3. Information provided must be an honest and accurate account of the accident. Any other information or statements of material facts may affect insurance coverability in the future.
4. The issue and acceptance of this Form by insurance companies is not an admission of liability on the part of the insured or the insurer.
5. This form must be filed with the Police or the LKK Auto Consultant.
6. This report will be forwarded by the Insurer of the LKK Auto Consultant to the General Insurance Association of Singapore (GIAS) for recording and that copies of this report will also be made available upon request to the Insurer.
7. In the absence of agreement to the Insurer, you hereby accept the conditions of coverage of the LKK Auto Consultant as a condition of the report being made available to you.

Date of Submission: 20/02/2014
 Date of Accident: 20/02/2014
 Exact Location of Accident: Singapore
 Additional Location(s): THE TOWARDS RT 2
 Country/State of Accident: Singapore

Vehicle Registration Number: 2002291
 Is compulsory? No
 Name of Reproductive Owner: Mr. H. H.
 NRIC No: S4002583
 Legal Address: 44/14-48
 Mobile Phone No: 97542288
 Alternative Phone No: 97542288

Witness Name: Mr. H. H.
 Name: Mr. H. H.
 Contact Number by which vehicle was being used at time of accident: 97542288
 Are you driving under your own insurance policy for report to your insurer? No

Name of Insurance Company: Allianz
 Type of Coverage: Comprehensive
 Fleet Policy: No
 Policy Number: SP200070379-01
 Cover Hole Number: 0000

Name of Driver: Mr. H. H.
 NRIC No: S4002583
 Date Of Birth: 15/01/1983
 Occupation: Driver

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

4414-48