

ASSIGNMENT

Estimated Cost:

TP/WS/TP RES/OD RES/EVA/INV/MV

Inspect Vehicle No:

Workshop m/s

Modern Vespa

Insured:

Policy No.

Claims No

S1M033PL

Insured:

Excess

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Actual or Market Value:

\$11K

JAC: Accident Report

Consistent? Yes or No

WIA / PR Seen.

Consistent? Yes or No

Est. Repairs

3

days

Res:

Yes or No

Sum Sum.

%

3 Val

Yes or No

CA / REV / REP. / 24 HRS

Date

Person Contacted

Vehicle: IN / OUT

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Piaggio Vespa

CC 155

Colour

Black

A/C Insured / Std / NI / NA

Sp Reading

T/Radio: Insured / Std / NI / NA

Eng/No

C/No:

ZAPMA120000004824

Gen Cond: Good / Fair / Poor / Burnt

Steering In order / Jammed / Leaked / Burnt or

Brake In order / Jammed / Leaked / Burnt or

Mod: S/Rim / STD A/Rim or

Tyre Size:

F:

110/70-11

R:

120/70-11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal

5

mm

R/Bal

5

mm

L/Bal

mm

L/Bal

mm

D.O.A

D.O.I

25-02-21

Survey held at

W/S

11:10

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

026: 2843

\$2000 - \$3000

23/03/21 @ 3.17pm revised to Jun Hong via Smart Claims.

23/03/21 Submit PRS.

Date/Time: File Pass to:

☐

: Preli. Report

23/03 Typist

☐

: Final Report

Date/Time: File Return to:

Days Of Repair: 3

Resurvey No. of Trip:

Survey Fee:

Transportation

Add Fee:

☐

Site Insp: \$

☐

Interview: \$

☐

Photograph: \$

☐

Other: \$

SMART CLAIMS -PRS