

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

Date: 16.02.2021
Time: 18:10:03
Page: 1

Lke

CHINA
PIP

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:45
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-2282-G	COVER-RR BUMPER#	1 L	459.40	20.00	367.52	/CRK
0002 04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60	/NEC
0003 04-01-0104-2531-G	BRACKET ASSY-RR BUMPER SI	1 L	55.80	20.00	44.64	?
0004 04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1 L	451.25	20.00	361.00	/CRK
0005 04-01-0104-2544-G	CAP-RR HOOK	1 L	98.80	20.00	79.04	?
0006 FNPS	NUMBER PLATE WITH TRIM CO	1 N	55.00	2.00-	55.00	/CRK
0007 09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1 L	40.50	20.00	32.40	?
0008 04-01-0104-2370-G	LAMP ASSY-REAR FOG	1 L	201.50	20.00	161.20	?
0009 09-01-9999-0068-A	REVERSE SENSOR ASSY*	1 N	180.00	2.00-	180.00	/MIS
0010 04-01-0104-2545-G	MOULDING-REAR BUMPER LWR	1 L	155.00	20.00	124.00	?
0011 04-01-0104-2540-G	COVER-RR BPR UNDER CTR	1 L	225.00	20.00	180.00	/DEF

SUB-TOTAL : 1,602.40

JOB NATURE

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305453938
REGN NO : SHA2227A
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 30.09.2020
DATE/TIME IN : 16.02.2021 10:4
ACCIDENT DATE : 16.02.2021

JOB / PARTS DESCRIPTION		QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0000 L	PANEL BEATING[repair rr fender Lh]	900.00		700		
0001 23-502	SPRAYPAINT ON AFFECTED AREA	550.00		400		500
0002 17-01	CHECK ALL LIGHTING	50.00		30		
0003 20-00	TUFF COAT ON AFFECTED PARTS.	50.00		40		
0004 20-22	REMOVE/REFIX REVERSE SENSOR	120.00		30		
SUB-TOTAL						: 1,670.00

TOTAL : 3,272.40

MVA NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE :

NA2 LKK

17/2/2021 1540

-P/R

3 DAYS

CHECK ITEM PHOTOS

BEFORE PAINT PHOTOS

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date/Time: 16.02.2021 17:33

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order:

JC NO: 305453938

COMFORT TRANSPORTATION PTE LTD
7010045
383 SIN MING DRIVE
Singapore SINGAPORE 575717
65508755

REGN NO: SHA2227A

MAKE: HYUNDAI

MODEL: IONIQ(G3)

YR OF MANU: 30.09.2020

CHASSIS CODE: KMHC851CVLU189599

MILEAGE

FUEL

DATE/TIME IN

TARGET DATE


COMPLETION DATE/TIME

CHINA

Accident Date: 16.02.2021
ATURE: 3P 16.02.2021

JOB DESCRIPTION

/NO LABOR CODE DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

Vehicle No.: SHA2227A

LKE

Vehicle No.:

SHA2227A

Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard