

DATE: 28.02.2021
DAY : Sunday

Workshop Accident Repair Estimate

ACCIDENT DATE	23.02.2021	BUS REGISTRATION NUMBER	SBS8529R
ACCIDENT TIME	21:00 HRS	BUS TYPE (DD OR SD)	SD
THIRD PARTY CLAIM AGAINST	PRIVATE CAR, SLT8576		

S/No	SECTION A :	PARTS & MATERIAL COST	
	SBS8529R, Scania KUB4X2, SD, AC, 2 Axle		
	Part or Item Description	Quantity	Total Cost
1	HEADLAMP COVER N/S;F/GLASS(100 BUSES) - 30 122 002	1 pc	\$ 296.40
2	HEADLAMP COVER O/S;F/GLASS; C - 30 122 054	1 pc	\$ 210.60
3	LAST ITEM		\$ -
4			\$ -
5			\$ -
6			\$ -
7			\$ -
8			\$ -
9			\$ -
10			\$ -
11			\$ -
12			\$ -
13			\$ -
14			\$ -
15			\$ -
		TOTAL PARTS & MATERIAL COST	\$ 507.00

	SECTION B:	ASSESSMENT/REPAIR/SPRAY PAINT (LABOUR COST)	
	Labour		\$ 1,874.60
	Spray Painting		
	Vinyl		
	Advertisement		
		TOTAL LABOUR COST	\$ 1,874.60

	SECTION C :	SUMMARY	
		TOTAL REPAIR COSTS	\$ 2,381.60
		TOTAL DOWNTIME	2.0 days

NOTE:

- 1) Repair cost is excluding Loss of use.
- 2) Additional parts might be required during the course of repair.