Messages

Claims



General & Workshop [Vehicle Condition Taxes & I	Ratio Parts & Labour Miscellaneous
General Details	Summary	Workshop De	etails
nvolving	TPVD YAMAHA T150 (FBR4608C)	Total Rebate	0
Date of Loss	12 February 2021	Amount	
ime of Loss	15:15	Nett Loss Amou	unt \$0.00
oss Description	ED66E (INSD) C/W FBR4608C (TF	Assigned Works	shop LKK AUTO CONSULTANTS PTE LTD (TP)
Comment		Days of work completion *	20



Messages

Claims



General & Workshop	Details Ve	hicle & Driver Details	Vehicle Co	ndition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary					
/ehicle & Driver De	tails							
/ehicle Registration#	FBR4608C			Puro	chase Date	DD/MM/YYYY		ı
Registration State	SINGAPOF	RE		Reg	istration Date *	14/07/2020		
Mileage	13473			Age	of Vehicle	0		
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMAT	ΓΙΟΝ	Dri	ver Details			
Manufacturing Year		2020		(CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION	
				[Driver Name	MUHAMMED GHAZALI		

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Make	TPVD YAMAHA	YAMAHA	Date of Birth		DD/MM/YYYY
Model	T150	T150	Age	0	
Туре		~	Occupation	Unknown	
Type of Paint			Education Qualification	Other	•
Chassis No		MH3UG131000001373	Driving Experience	0	
Engine No		G3P3E0001397	Driver License #		
Engine Capacity		150	License Type		~
Sum Insured		0	License Issue Date		DD/MM/YYYY

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		0

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		DD/MM/YYYY
Address	Singapore	
Address type	Personal Correspondence	~
Gender	Unknown	~
Marital status	Unknown	~
Identification #	S9928419F	

Messages

Claims



General & Workshop De	tails Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	
			Summary			
Detailed Assessment		Со	ndition of Vehicle	e at time of surve	⊇y	
Inspection Date *	26/02/2021	Ge	neral condition	Good		~
Total Loss	Yes No	Ste	ering (Serviceable)	Yes	No	
Towing Charges	0		otbrake rviceable)	Yes	No	
Voluntary Excess	0		ndbrake rviceable)	Yes	No	
Compulsory Excess	0	Enį	gine Modification	Yes	No	
Young/Inexperienced/ Unnamed Driver Excess	0	Pre	e-accident condition	Good		~

Other Excess	0

Tyre Condition Age of Tyres Front Tyre Size 90/80-17 Front left side IRC4mm Front right side Spare wheel Rear Tyre Size 120/70-17 Rear left side IRC4mm Rear right side

Messages

Claims



General & Workshop D	etails	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
					Summary	
Tax Eligibility & Addit	ional [Deduction for Parts				
Depr./Bttr%	0		Sa	vage%	0	
Discount%	10		Set	tlement%	100	
			Paint l	.abour/Material F	Ratio	
Paint Labour Ratio	20		Ca	sh Loss	Yes	No
Paint Material Ratio	80		Pal	t Supplied by AXA	Yes	No
						Save

Messages

Claims



Add		Appro	ove	Deny	Submit Al	II							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTE AMOUNT
	0	1		FRONT MUDGUARD	Cut	0	185	No	0	10	0	0	166.5
	0	1		FRONT DISK	Serviceable	0	0	No	0	0	0	0	0
	0	1		FRONT WHEEL AXLE	Serviceable	0	0	No	0	0	0	0	0
	0	1		RIGHT FORK ASSEMBLY	Repair	0	0	No	0	0	0	0	0
	0	1		LEFT FORK ASSEMBLY	Repair	0	0	No	0	0	0	0	0
	0	1		FRONT FAIRING COVER OUTER	Cut	0	165	No	0	10	0	0	148.5

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		FRONT FAIRING COVER EMBLEM	Serviceable	0	0	No	0	0	0	0	0	Di
	0	1		FRONT FAIRING COVER INNER	Deformed	0	135	No	0	10	0	0	121.5	R€
	0	1		FRONT LEFT FAIRING ASSEMBLY	Broken	0	280	No	0	10	0	0	252	Rŧ
	0	1		FRONT RIGHT FAIRING ASSEMBLY	Broken	0	280	No	0	10	0	0	252	Re
	0	1		HEADLAMP ASSY	Damaged	0	335	No	0	10	0	0	301.5	Rı
	0	1		FRONT HEADLIGHT COVER	Cut	0	188	No	0	10	0	0	169.2	Rí
	0	1		METER OUTER COVER	Cut	0	155	No	0	10	0	0	139.5	Rŧ
	0	1		METER INNER COVER	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		METER ASSY	Serviceable	0	0	No	0	0	0	0	0	Di

EDI	IT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	,	0	1		CENTRE INNER FAIRING	Serviceable	0	0	No	0	0	0	0	0	D١
	·	0	1		YAMAHA EMBLEM	Serviceable	0	0	No	0	0	0	0	0	Dı
	·	0	1		RADIATOR ASSY	Serviceable	0	0	No	0	0	0	0	0	Di
	•	0	1		BRAKE PUMP ASSY	Serviceable	0	0	No	0	0	0	0	0	Dı
	•	0	2		STEERING STEM BEARING	Serviceable	0	0	No	0	0	0	0	0	Di
	•	0	1		STEERING STEM BRACKET ASSEMBLY	Serviceable	0	0	No	0	0	0	0	0	Dı
	>	0	1		HANDLE BAR	Serviceable	0	0	No	0	0	0	0	0	Dı
	>	0	1		SET BALANCER	Cut	0	88	No	0	10	0	0	79.2	Rŧ
	>	0	1		BRAKE LEVER	Cut	0	115	No	0	10	0	0	103.5	Rí
•		0	1		SET REAR VIEW MIRROR	Broken	0	165	No	0	10	0	0	148.5	Rı

EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	AC (P.
	0	1		FRONT FOOTREST HOLDER ASSEMBLY	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		BRAKE PEDAL ASSY	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		GEAR SHIFTER PEDAL ASSY	Bent	0	135	No	0	10	0	0	121.5	Rŧ
	0	1		REAR LEFT FAIRING ASSEMBLY	Cut	0	280	No	0	10	0	0	252	Rŧ
	0	1		REAR RIGHT FAIRING ASSEMBLY	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		LEFT REAR FOOTREST	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		RIGHT REAR FOOTREST	Serviceable	0	0	No	0	0	0	0	0	Dı
	0	1		SET REAR SIGNAL LIGHT	Cut	0	165	No	0	10	0	0	148.5	Rŧ
	0	1		SWING ARM ASSY	Cut	0	600	No	0	10	0	0	540	Rŧ
Labour														

Add Approve Deny Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TOWING CHARGES	0	50	0	0	Reviewing		
	0		DISMANTLE, REPLACE, REALIGN AND ADJUST ABOVE DAMAGED PARTS	0	200	0	0	Reviewing		
	0		TO KNOCK, STRAIGHTEN CHASSIS & BODY BALANCING	0	0	0	0	Deny		
	0		TO REMOVE / REFIT, REPLACE CHECK AND STRAIGHTEN FRON FORK TUBES	0	100	0	0	Reviewing		
	0		TO REMOVE / REFIT AND BALANCE FRONT SPORT RIM	0	0	0	0	Deny		
	0		SPRAY PAINTING	0	0	0	0	Deny		

Messages

Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary

Add		Approve	D	eny	Submit All		
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR: 3 DAYS	Reviewing	0	0		
	0	ERP IU	Deny	0	0	NOT NECESSARY	
	0	REAR NUMBER PLATE	Reviewing	0	10	CUT	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	FRONT / REAR SPORT RIM (2PCS)	Deny	0	0	NOT NECESSARY	
	0	FRONT / REAR TYRE (2PCS)	Deny	0	0	NOT NECESSARY	
	0	COOLANT	Deny	0	0	NOT NECESSARY	
	0	FORK OIL	Deny	0	0	NOT NECESSARY	
	0	BRAKE FLUID	Deny	0	0	NOT NECESSARY	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	LEFT FAIRING ASSEMBLY LABELS STICKER	Reviewing	0	100	SCRATCHED	
	0	RIGHT FAIRING ASSEMBLY LABELS STICKER	Deny	0	0	NOT NECESSARY	



Messages

Claims



Assessment Details

General & Workshop D	etails	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Adju	usted Claim Amoun	t \$3,403.90	
CATEGORY		ESTIMATE	ADJUSTED			
Spare Parts		\$0.00	\$2,943.90			
Labour		\$0.00	\$350.00			
Miscellaneous		\$0.00	\$110.00			

Submit for Review



Messages


Claims



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous

Summary



Messages

Claims



Assessment Details

General & Workshop	Details	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous
Summary						
Estimated Claim Amount	\$0.00		Ad	justed Claim Amount	\$2,700.00	
CATEGORY		ESTIMATE	ADJUSTED			
Miscellaneous		\$0.00	\$2,700.00			

Submit for Review