SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 25/02/2021 14:46 (SGT) Date of Accident 25/02/2021 08:00 (SGT) Exact Location of Accident CTE, Singapore Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number **GBF3775Y**

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner MAINLAND ENGINEERING PTE LTD

Company Reg No

Email Address TAY08323@GMAIL.COM Mobile Phone No (Phone) +65-68481131 Alternative Phone No +65-68481131

VEHICLE PARTICULARS

Manufacturer Toyota Model Hiace Variant

Exact purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

No - Claiming third party Commercial vehicle

Employment

INSURANCE COMPANY


Name of Insurance Company Liberty Insurance Type of Coverage Comprehensive Fleet Policy

Policy Number SD20V09686/VCV/R00

Cover Note Number

DRIVER

Name of Driver **CHUNG SIE UNG** NRIC No SXXXX302H Date Of Birth 26/04/1977 Occupation Indoor



Date Of Driving Pass 03/12/2007 Driving experience 13 YEARS AND 2 MONTHS Gender Mobile Number (Phone) +65-92257339 Alt. Phone Number Email Address TAY08323@GMAIL.COM Address BLK 727 YISHUN ST 71 #03-97 Address complement Postcode 760727 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO STATEMENT. ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Nο Was there any audio recorded? No **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SGT7840H
Vehicle Manufacturer	_
Vehicle Model	
	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	_
Address complement	
	-
Postcode	-
Insurance Company Name	-

Nature Of Damage	_
Details of property damaged in accident	_
No. Of Passenger (Including Driver)	_

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLM946K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	CHUNG SIE UNG
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	BODY
Injured person in which vehicle?	GBF3775Y
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the hourers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

MAINLAND ENGINEERING PTE, LTD s sins close #02-02 GEMINI & SINS SINGAPORE 387298 TEL: 6848 1131 FAX: 6848 1121

9x


H

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel





1	was	tra	ivelling.	along	CTE	near	braddell	Rol
Exit	on	the.	Farm	4th Lo	ne,	Veh (c which u	vas infron
of	ме	Slow	down a	nd Ste	p. I	foll	w +0 S10	w down
and	Stop	. А	ll of a	Sudder	, 1	felt	an impact	from
behi.	· d .	due	to the	impac	/ m	y veh	been push	forward
hrt	onto	veh	C , Af	ter the	incid	en t	Z realiz	ed veh
R	From	behi	nd coll.	ded on	to my	veh	rear por	tion.
		-						
+								
Sell Control								
-		_			-			
-	-							
					VVE. (200)			
					-			

Driver's Signature (if driver is not the policyholder) / Date & Time

MAINLAND ENGINEERING PTE, LTD. 2 SIMS CLOSE #02-02 GF/MNI 0 SIMS SINGAPORE 367298 TEL: 6848 1131 FAX: 6848 1121

Policyholder's Signature / Date & Time Witnessed by Reporting Centre Personnel























