

# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL: 6849 8118

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

ATTN:

TP INS. CO.

FAX:

YOUR REF NO : SLL2123K

**CLAIM TYPE** : THIRD PARTY

ACCIDENT DATE : 22/02/2021

TP VEH REG NO : SLL2123K

# **ESTIMATE**

NO : QUOT202102-000064(00)

DATE : 24/02/2021 POLICY NO : 999995580 VEH REG NO : GBH7542R

MAKE/MODEL: MERCEDES BENZ VITO 109

CDI MT LONG

CHASSIS NO : WDF44760323474388

: R9MA503C052160 **ENGINE NO** REG. DATE : 2018

# Estimate Repair Cost to Vehicle No: GBH7542R

	Description	Quantity	Unit Price	Amount
			<u>\$\$</u>	<u>S\$</u>
1	NET PRICE	4	1 950 00	1 950 00
1	Dashboard assy	1	1,850.00	1,850.00
2	Steering air bag	1	2,455.00	2,455.00
3	Passenger air bag	1	2,455.00	2,455.00
4	Air bag control unit	1	1,495.00	1,495.00
5	Front safety belt - RH / LH	2	790.00	1,580.00
6	Front safety belt buckle - RH	1	485.00	485.00
7	Front safety belt adjuster - RH / LH	2	285.00	570.00
8	Front safety belt - centre	1	790.00	790.00
9	Front safety belt buckle - LH	1	325.00	325.00
10	Front safety belt buckle - centre	1	325.00	325.00
11	Battery cut off switch	1	520.00	520.00
12	Bonnet	1	1,475.00	1,475.00
13	Bonnet lock - lower	1	185.00	185.00
14	Bonnet hinge - RH / LH	2	80.00	160.00
15	Support panel	1	590.00	590.00
16	Support panel top garnish	1	115.00	115.00
17	Support panel bracket - LH	1	48.00	48.00
18	Front fender - LH	1	788.00	788.00
19	Front fender inner shield - LH	1	188.00	188.00
20	Front fender inner shield flap - LH	1	58.00	58.00
21	Front fender inner shield clips - LH	20	9.00	180.00
22	Headlamp assy - LH	1	845.00	845.00
23	Front bumper	1	965.00	965.00
24	Front bumper reinforcement	1	680.00	680.00
25	Front bumper carrier - LH	1	104.00	104.00
26	Front bumper side retainer - LH	1	98.00	98.00
27	Front bumper strut - LH	1	64.00	64.00
28	Front bumper cross member bracket - LH	1	74.00	74.00
29	Front bumper under cover	1	265.00	265.00
30	Front bumper lower cross member	1	290.00	290.00
31	Front bumper clips	15	9.00	135.00
32		1	145.00	145.00



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

**ESTIMATE** 

POLICY NO

REG. DATE

NO

DATE

PAGE: 2

: QUOT202102-000064(00)

: 24/02/2021

: 999995580

MAKE/MODEL: MERCEDES BENZ VITO 109 **CDI MT LONG** 

CHASSIS NO : WDF44760323474388 ENGINE NO : R9MA503C052160

: 2018

VEH REG NO : GBH7542R

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER SINGAPORE 608531

TEL : 6849 8118

ATTN:

FAX:

YOUR REF NO : SLL2123K

**CLAIM TYPE** 

: THIRD PARTY

TP INS. CO.

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 22/02/2021 TP VEH REG NO : SLL2123K

# Estimate Repair Cost to Vehicle No: GBH7542R

	Description	Quantity	<b>Unit Price</b>	Amount
			<u>S\$</u>	S\$
33	Washer tank neck	1	58.00	58.00
34	Washer tank cover	1	28.00	28.00
35	Air-con condenser	1	650.00	650.00
36	Air-con condenser support frame	. 1	165.00	165.00
37	Radiator assy	1	660.00	660.00
38	Radiator auto fan assy	1	980.00	980.00
39	Radiator guide - LH	1	78.00	78.00
40	Radiator lower cover	1	125.00	125.00
41	Radiator support - LH	1	48.00	48.00
42	Radiator top clips - LH	1	28.00	28.00
43	Radiator top bearing - LH	1	58.00	58.00
44	Inter-cooler assy	1	780.00	780.00
45	Front shock absorber - LH	1	1,515.00	1,515.00
46	Front upper arm - LH	1	1,210.00	1,210.00
47	Front lower arm - LH	1	1,250.00	1,250.00
48	Front knuckle arm - LH	1	2,315.00	2,315.00
49	Steering tie-rod - LH	1	280.00	280.00
50	Steering tie-rod end - LH	1	198.00	198.00
51	Front torsion bar	1	340.00	340.00
52	Front linkage - LH	1	111.00	111.00
53	Sub frame	1	2,030.00	2,030.00
54	Front axle	1	2,870.00	2,870.00
55	Front wheel rim - LH	1	380.00	380.00
56	Front wheel hup cap - LH	1	88.00	88.00
			_	36,547.00
			Less 10%	3,654.70
			_	32,892.30
	SPECIAL NET			
57	Front windscreen sealant	1	60.00	60.00
58	Radiator coolant	2	60.00	120.00
59	Front tyre - LH	1	280.00	280.00
60	Front number plate	1	40.00	40.00
61	ERP bracket	1	26.00	26.00
				526.00



# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545 Email: operation@tlauto.com.sg GST No: 201700521W UEN No: 201700521W

PAGE: 3

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE

#15-08 WESTGATE TOWER

SINGAPORE 608531

TEL : 6849 8118

FAX:

ATTN:

: SLL2123K

YOUR REF NO **CLAIM TYPE** 

: THIRD PARTY

TP INS. CO.

: AIG ASIA PACIFIC INSURANCE PTE. LTD.

ACCIDENT DATE : 22/02/2021 TP VEH REG NO : SLL2123K

**ESTIMATE** 

NO

: QUOT202102-000064(00)

DATE

: 24/02/2021

POLICY NO

: 999995580

: 2018

VEH REG NO : GBH7542R

MAKE/MODEL: MERCEDES BENZ VITO 109

CDI MT LONG

CHASSIS NO : WDF44760323474388

**ENGINE NO** REG. DATE

: R9MA503C052160

Estimate Repair Cost to Vehicle No: GBH7542R

	Description	Quantity	Unit Price	Amount
			<u>S\$</u>	<u>S\$</u>
	LABOUR			
62	To remove and refit front windscreen glass	1	150.00	150.00
63	To remove and refit front dashboard assy, meter and grove compartment	1	350.00	350.00
64	To remove and refit air-con condenser, radiator, inter-cooler assy and refill air-con gas	1	280.00	280.00
65	To check and rectify wiring systems	1	80.00	80.00
66	To remove and refit steering air bag, passenger air bag, airbag control unit, front both side and centre safetly belt	1	550.00	550.00
67	To remove and refit battery cut off switch	1	150.00	150.00
68	To remove and refit LH front undercarriage	1	580.00	580.00
69	To panel beat and straighten LH front chassis frame, LH front fender inner panel, including replacement of parts and align where necesary, to refit and adjust the same	1	1,500.00	1,500.00
70	To putty and spray paint on affected areas	1	1,200.00	1,200.00
71	To re-programe and coding all faulty code (online)	1	580.00	580.00
72	To check wheel alignment	1	100.00	100.00
			-	5,520.00
			TOTAL	S\$ 38,938.30
			ADD GST @ 7%	2,725.68
			GRAND TOTAL	S\$ 41,663.98

SINGAPORE DOLLAR FORTY-ONE THOUSAND SIX HUNDRED SIXTY-THREE AND CENTS NINETY-EIGHT ONLY

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE

# TOMOLUGAANO

# TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722
Tel: 6250 0088 Fax: 6250 5545
Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

AIG ASIA PACIFIC INSURANCE PTE. LTD. 78 SHENTON WAY #07-16 AIG BUILDING SINGAPORE 079120 25 February 2021

Attn: MOTOR CLAIM DEPT

Dear Sirs / Madam,

RE: ACCIDENT INVOLVING VEHICLE NO.: GBH7542R & SLL2123K ON 22/02/2021 @ 09:00 HRS ALONG DEFU AVENUE 2

We hereby authorized by our client **DAIMLER FLEET MANAGEMENT S'PORE PTE LTD**, the owner/driver of the above mentioned vehicle No.: **GBH7542R** 

We notice that the above accident was caused by your insured/driver negligent driving and/or management of motor vehicle No.: SLL2123K

Therefore we are instructed by our client to claim against you/your insured driver in connection with the above captioned accident involving our client's vehicle No.: **GBH7542R** and vehicle No.: **SLL2123K** by your insured/driver at the material time. As a result, our client's vehicle was damaged and our client has been put to loss and expenses. Please assign your surveyor to inspect the above mentioned vehicle in the next 48hrs. Filling which, we will proceed to the repair of the vehicle. Details of claim will submitted to you in due course.

The vehicle is now garage at:

TONG LUCK AUTO PTE LTD

160 Sin Ming Drive

#07-01/06 Sin Ming Autocity

Singapore 575722 Tel: 6250 0088

Your kind attention to the matter would be much appreciated.

Yours faithfully,

TONG LUCK AUTO PTE LTD

SA0A212N000C / Ajax Mars Pte Ltd ENTRY DATE & TIME: 23/02/2021 21:11 (SGT) SUBMITTED BY: Sharil VERSION: 1 (23/02/2021 21:11 (SGT))



# SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
  3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 5. Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving
- and that copies of this report will, for a fee, be made available upon application by interested parties.

  7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

# ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information Country/State of Loss

23/02/2021 21:11 (SGT) 22/02/2021 09:00 (SGT) Defu Ave 2, Singapore ALONG DEFU AVENUE 2

Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**GBH7542R** 

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

Company Reg No

Email Address

Mobile Phone No Alternative Phone No Yes

DAIMLER FLEET MANAGEMENT SINGAPORE PTE, LTD.

1XXXXX778Z

faizal.mohamed@daimler.com

(Phone) +65-68498118 (Office) +65-68498118

VEHICLE PARTICULARS

Manufacturer Model

Variant Exact purpose for which vehicle was being used at time of

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category Mercedes Vito

Private hire

No - Claiming third party Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy Policy Number Cover Note Number

Yes

AIG

999995580

Comprehensive

NA

DRIVER

Name of Driver NRIC No Date Of Birth Occupation

DEN DIRZUAN BIN DARMAWAN SXXXX221J 27/09/1987 Outdoor



Date Of Driving Pass

18/05/2018 Driving experience 2 YEARS AND 9 MONTHS

Gender

Mobile Number

Alt. Phone Number

**Email Address** 

Address

buayedecent@gmail.com

(Phone) +65-89225125

HDB Ang Mo Kio View, 203 Ang Mo Kio Avenue 3 560203 #05-

1716

Nο

Nο

Hirer

Male

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Weather Conditions Road Surface

Side Swipe Clear Dry

No

Yes

Yes

Yes

No

OTHER INFORMATION

Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident

Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance?

Was any other material or property damaged? Number of Passengers (Including Driver)

Has the driver been approached by unknown person(s)

soliciting/offering accident claims assistance?

DETAILS OF POLICE ACTION

Was the accident reported to the police?

Police Station Name Police Station Phone No

Alt. Police Station Phone No.

Police Station Address

Was notice of intended Prosecution given?

If yes, against whom?

Jurong West Neighbourhood Police Centre

(Phone) +65-18002689999

(Fax) +65-62672438

700 Corporation Road Singapore 649818

No

CIRCUMSTANCES OF ACCIDENT

ON 22/02/2021 AT ABOUT 0900HRS,I WAS DRIVING MY COMPANY VEHICLE, GBH7542R, ALONG DEFU AVE 2 TOWARDS TAMPINES RD ON THE RIGHT LANE OF 2 LANES.AS APPROACHING X-JUNCTION OF DEFU AVE 2 AND DEFU LANE 1, I NOTICED THERE WAS A VEHICLE ,SLL2123K,STOP AT THE JUNCTION ON MY LEFT OF DEFU LANE 1.I THEN PROCEED DRIVING MY VEHICLE AS I WAS ON MAJOR ROAD. SUDDENLY, AS I WAS ABOUT TO PASS THE X-JUNCTION, THE VEHICLE MOVED FORWARDS.I THEN UNABLE TO AVOID IT, HENCE THE SAID VEHICLE COLLIDED ON THE LEFT SIDE OF MY VEHICLE WHICH THEN WAS PUSHED TOWARDS THE LANE OF THE OPPOSITE DIRECTION.AS I WAS UNABLE TO MOVE, PASSER BY ASSITED ME TO ALIGHT FROM MY VEHICLE.A WITNESS APPROACHED ME AND INFORMED HIS NAME AND NUMBER.HE TOLD ME THAT HE WAS BEHIND THE SAID VEHICLE AND HAD OBSERVED ACCIDENT THAT HAPPENED.MOMENTS LATER, AMBULANCE CAME AND ACCESS ME. I WAS TOLD THAT I WILL BE CONVEYED TO HOSPITAL. I SUSTAIN SWELLS ON MY RIGHT WRIST, RIGHT ELBOW, RIGHT SHOULDER AND RIGHT KNEE. I WAS CONVEYED TO SENGKANG GENERAL HOSPITAL AND WAS GIVEN 5 DAYS OF MEDICAL CERTIFICATE 22/02/2021-26/02/2021. I WISH TO STATE THAT I DID NOT MANAGE TO GET THE PARTICULAR OF THE OTHER DRIVER.MY VEHICLE DOES NOT INSTALL WITH AN CAR-CAMERA.

ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?

Yes Yes No

Accident report SA0A212N000C

Page 2 of 29

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration NumberSLL2123KVehicle ManufacturerMiniVehicle ModelCooperVehicle Variant-

Vehicle Colour

Vehicle Category Private car

Name of Driver Contact Number Address -

Address complement Postcode -

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

-

## INJURED PERSONS DETAILS

INJURED 1

Name of injured person DEN DIRZUAN BIN DARMAWAN

Address Complement

Address Complement Post Code Approximate Age Years Old -

Injuries Sustained

Injured person in which vehicle?

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

GBH7542R

Yes

### SKETCH PLAN

### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time: Driver's Signature (If driver is not the policyholder) Date & Time:


23 Feb 2021


VERIFY BY AJAX MARS (ARC) REPORTING OFFICER

MOHAMED SAIFULLAH S/O SYED MASOOD

Reporting Centre Personnel's Signature Name: NRIC/FIN No.:

SKETCH PLAN	
Date L	Une 1  Out Lone 2  Vehicle A GBH 7542R  Vehicle B, SLL 2123K  Dell Avenue 2.
DESCRIBE CIRCUMSTANCE	S OF THE ACCIDENT
REFER TO ATTACHED STAT	EMENT.
The second second	
DECLARATION  I/We declare the foregoing part	titulars are true to evary respect.  VERIFY BY AJAX MARS (ARC)  REPORTING OFFICER  MOHAMED SAIFULLAH S/O SYED MASOOD
Policyholder's Signature	Driver's Signature  Driver's Signature  (if driver's fact the policyholder)  Name:  NRIC/F-N No.





### Brief Details.

On 22/02/2021 at about 0900hrs, I was driving my company vehicle, GBH7542R, along Defu Ave 2 towards Tampines Rd on the right lane of 2 lanes. As approaching X-junction of Defu Ave 2 and Defu Lane 1, I noticed there was a vehicle, SLL2123K, stop at the junction on my left of Defu Lane 1. I then proceed driving my vehicle as I was on Major road. Suddenly, as I was about to pass the X-junction, the vehicle moved forwards. I then unable to avoid it, hence the said vehicle collided on the left side of my vehicle which then was pushed towards the lane of the opposite direction.

As I was unable to move, passer by assisted me to alight from my vehicle. A witness approached me and informed his name and number. He told me that he was behind the said vehicle and had observed the accident that happened. Moments later, Ambulance came and access me. I was told that I will be conveyed to hospital. I sustain swells on my right wrist, right elbow, right shoulder and right knee. I was conveyed to Sengkang General Hospital and was given 5 days of medical certificate 22/02/2021 - 26/02/2021. I wish to state that I did not manage to get the particular of the other driver. My vehicle does not install with an in-car camera.

