

ASS. REC. BY:

REF:

A6/ 21002031/k6

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLV 4761C

Yr Regn:

12, 17

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Volkswagen

Golf

c.c.

999

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

61448

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WVW 222 AUF JW 090429

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD ☒ A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / ☒ PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

2

mm

L/Bal.

5

mm

L/Bal.

2

mm

D.O.A.

24/2/21

D.O.I.

1/3/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S 1st & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

213

L12m @ 4350h. Cabin

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fines

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

WEGA ENGINEERING PTE LTD

Blk 176 Sin Ming Drive #04-16 Sin Ming Autocare Singapore 575721

Tel: 6452 1493

Fax: 6452 9153

GST Reg: 19-9900741 / Z

Claim Ref:

AIG ASIA PACIFIC

78 Shenton Way, # 11-16 Singapore 079120

Date : 25/2/2021

Vehicle No : SLV4761C
Chassis No : WVVZZZAUZJW090429
Make/Model : VOLKSWAGEN GOFT
Year :

*Not Authorized
61 Rps @ 4350/h
Paying After Paim*

-5 days

S/N	Qty	Description	Unit Price	Amount	
1	1pc	FRONT BUMPER	\$ 1,140.00	\$ 1,140.00	✓
2	1pc	FRONT HEADLAMP RH	\$ 761.00	\$ 761.00	✓
3	1pc	FRONT FENDER RH	\$ 649.00	\$ 649.00	✓
4	1pc	FRONT HEADLAMP BRACKET RH (TOP PANAL)	\$ 61.00	\$ 61.00	X
5	1pc	FRONT BUMPER BRACKET RH	\$ 53.00	\$ 53.00	✓
6	1pc	FRONT FOG LAMP COVER RH	\$ 104.00	\$ 104.00	X
7	1pc	FRONT FOG LAMP RH	\$ 245.00	\$ 245.00	X
8	1pc	FRONT SPORT RIM RH	\$ 1,473.00	\$ 1,473.00	X
9	1pc	FRONT TYRE RH	\$ 225.00	\$ 225.00	X
10	1pc	FRONT KNUCKER ARM RH	\$ 758.00	\$ 758.00	✓
11	1pc	FRONT WHEEL HUP RH	\$ 589.00	\$ 589.00	✓
12	1pc	FRONT WHEEL BEARING RH	\$ 280.00	\$ 280.00	✓
13	1pc	FRONT LOWER ARM RH	\$ 487.00	\$ 487.00	✓
14	1pc	FRONT ABSORBER RH	\$ 484.00	\$ 484.00	✓
15	1pc	FRONT TIE ROD RH	\$ 166.00	\$ 166.00	X
16	1pc	FRONT TIE ROD INNER RH	\$ 122.00	\$ 122.00	X
18	1pc	FRONT TORSION BAR LINK RH	\$ 125.00	\$ 125.00	X
19	1pc	FRONT DRIVE SHAFT ASSY RH	\$ 2,676.00	\$ 2,676.00	X

Bumper

61

R

R

R

R

R

R

R

R

R

R

R

R

R

R

R

108

Labour Charges

1	To check wiring and system function	\$ 120.00	<i>201</i>
2	To wheel alignment / tyre balancing	\$ 120.00	<i>201</i>
3	To remove and refix undercarriage	\$ 600.00	<i>2001</i>
4	To respray accident front portion	\$ 1,000.00	<i>4001</i>
5	To knocking and welding front portion	\$ 1,000.00	<i>4001</i>
6	To apply rust proofing to affected area	\$ 150.00	<i>301</i>
7	To replace front tyre	\$ 55.00	<i>✓</i>
	To check for function and alignment headlamp	\$ 80.00	<i>✓</i>

Grand Total

\$ 13,523.00

Wega Engineering Pte Ltd

Authorised Signature

Leong Chee Kwong

Mobile No: 84917768

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

555C

Vehicle Details

Vehicle No.:

SLV4761C

Vehicle to be Exported:

No

Intended Deregistration Date:

25 Feb 2021

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

GOLF TSI TL

Primary Colour:

Red

Manufacturing Year:

2017

Engine No.:

CHZ584044

Chassis No.:

WVWZZZAUZJW090429

Maximum Power Output:

81.0 kW (108 bhp)

Open Market Value:

\$18,520.00

Original Registration Date:

29 Dec 2017

First Registration Date:

29 Dec 2017

Transfer Count:

0

Actual ARF Paid:

\$8,520.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

28 Dec 2027

PARF Rebate Amount:

\$6,390.00

Intended COE Rebate Details

COE Expiry Date:

28 Dec 2027

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$38,200.00

COE Rebate Amount:

\$26,134.00

Total Rebate Amount:

\$32,524.00

The information contained herein is correct as at 25 Feb 2021

OK