



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21002644/Avf3n2 Date: 24/05/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGJ 6473T	Veh. Inspected	SMM 4481X	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10009157/SH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	26/02/2021	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT GRAND SCENIC	c.c	1461	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	VF1RFA00X62673000	Colour	GREY	
Odometer	128946 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R20	CONTINENTAL	6 mm	
L/H Front Tyre	195/55 R20	CONTINENTAL	6 mm	
R/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm	
L/H Rear Tyre	195/55 R20	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/02/2021	Inspection Date	26/02/2021	
Survey held at	XIN HUA WORKSHOP PTE LTD 23 KAKI BUKIT AVENUE 4 #04-01 (SOUTH WING) SINGAPORE 415933			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			10 Working Days	