

ASS. REC. BY:

REF: CS3/ASM21002655/Gvf3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)From (Person): Dominic Yu of ASM Date/Time: 26/02/2021

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: FX 898D Insured: SHC 3998Rat Workshop m/s EQUATOR BROTHERHOOD Tel: 90113391of 25 KAKI BUKIT RD #03-79 SYNERGY @ KBPolicy No: _____ Claim No: S1M032ZM

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS 'PRS'

H.O.D. Endorsement: _____

Date/Time: 26/02@12pm Person Contacted: WILLE Vehicle ☒ IN / ☐ OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	FX 898D-X
	SHC 3998R - CC/CTI18011184/K1wa3n2 DOA: 18/06/2018
2/3/21	Send IA via Smart Claim
2/3/21	Submit PRS, repair range \$2,000-\$3,000 (3 days)

Smart Claims