

ASS. REC. BY:

REF: CS/CTI21002665/T1qf3

Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person): Irene Tay of CTI Date/Time: 26/02/2021@2.52pm

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: XE 3875L Insured: SJV 5988H

at Workshop m/s WAH HONG MOTORS & CREDIT Pte Ltd Tel: 87783338

of 38 TOH GUAN ROAD EAST #01-57

Policy No: DMPCSNW00011072100 Claim No: SNM21D201011C02

Sum Insured: Excess:

Make of Veh: D.O.A. 21/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS WP appt 01/03/21@10.30am H.O.D. Endorsement:

Date/Time: Person Contacted: Melvin Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (☒) Estimate
	XE 3875L-X
	SJV 5988H -X