



WAH HONG MOTORS & CREDIT PTE LTD

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. TRD4549Z ZENITH 27KL ALU DIESEL TANKER TRAILER

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
1	<u>PARTS (LIST ITEMS)</u>		3000 4000.00	bt —
	Rear bumper, Rear crossbeam and lighting box		3000	
			4000.00	
			4000.00	
			4000.00	
1	<u>SPECIAL NETT ITEMS</u>			
	Rear carplate		35.00	bt —
	Rear tail lamp wiremesh cover		50.00	bt — 30
	Rear reflector sticker		80.00	net — 40
Total Parts			4165.00	

105



WAH HONG MOTORS & CREDIT PTE LTD

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg
(199806235M)

Vehicle No. TRD4549Z ZENITH 27KL ALU DIESEL TANKER TRAILER

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	1000.00	600
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (including caution wording & signal)	1000.00	500
3	To perform defilling of fuel & degassing and Tank Degassing Safety check	800.00	? 400 photo Xnn
4	To remove and re-fix wiring system at accident damaged area and check all electrical & component for proper function	400.00	40
5	To perform anti-rust treatment on affected areas	200.00	30
Labour Total :		3400.00	
TOTAL (PARTS & LABOUR):		7565.00	

1170

Taufik 17495749

WP 1/3/21 @ 1120

Resum new parts before paint

* To check pricing

Taufik @ 11hant.com

4 days

3000

105

1170

\$4275

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: