

ASS. REC. BY:

REF: CS/MSG21002666/AGqf3

Special Instruction:

Merimen

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): Douglas Ong of MSIG Date/Time: 26/02/2021

Estimated Cost: _____ Bill to: _____

OD TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLD 2656G Insured: SLS 3850B

at Workshop m/s Advance Auto Garage Tel: 90079247

of 10 Kaki Bukit Road 2, #01-21 First East Centre, 417868 Kaki Bukit

Policy No: 30001621471 Claim No: 253923

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 26/02/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement: _____

Date/Time: _____ Person Contacted: _____ Vehicle IN / OUT

Date/Time	Action/Instruction (<input checked="" type="checkbox"/>) Estimate
	SLD 2656G-X
	SLS 3850B-X