



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD Toyota Hiace (GBK6443J)
Date of Loss	5 January 2021
Time of Loss	9:59
Loss Description	SKX6075M (INSD) C/W - GBK6443J (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="0"/>
Nett Loss Amount	\$56,388.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	<input type="text" value="20"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# GBK6443J

Registration State

SINGAPORE

Mileage

19489

Purchase Date

DD/MM/YYYY



Registration Date *

07/10/2020



Age of Vehicle

0

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2020

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION





Driver Name

WEE GEM CHAI

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD Toyota	<input type="text" value="TOYOTA"/>
Model	Hiace	<input type="text" value="HIACE VAN TURBO 5Df"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="JTFHT02P609990451"/>
Engine No		<input type="text" value="1KDB048196"/>
Engine Capacity		<input type="text" value="2982"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	13 December 1967	<input type="text" value="DD/MM/YYYY"/> 
Age	53	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="81000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value=""/> 
Gender	Unknown	<input type="text" value=""/> 
Marital status	Unknown	<input type="text" value=""/> 
Identification #	S1819607G	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

02/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

195 R15

Front left side

BRIDGESTONE6mm

Front right side

BRIDGESTONE6mm

Spare wheel

Rear Tyre Size

195 R15

Rear left side

BRIDGESTONE6mm

Rear right side

BRIDGESTONE6mm



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

0

Salvage%

0

Discount%

0

Settlement%

100

Paint Labour/Material Ratio

Paint Labour Ratio

20

Cash Loss

Yes

No

Paint Material Ratio

80

Part supplied by
P
a
r
t
S
u
p
p
l
i
e
d
b
y

A
X
A

Save



Service Requests

Messages

Claims





<< Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Parts

Add		Approve		Deny		Submit All								
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)

Labour

Add		Approve		Deny		Submit All				
EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		LABOUR TO KNOCK DENTED REAR DOOR	0	200	0	0	Reviewing		
	0		PUTTY & RE-SPRAY PAINTING REAR DOOR AFTER KNOCKING	0	300	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

DAYS
OF
REPAIR
: 3
DAYS

Reviewing

0

0





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$500.00
------------------------	--------	-----------------------	----------

CATEGORY

ESTIMATE

ADJUSTED

Labour

Submit for Review