

ASS. REC. BY: Marcus

REF:

CS/1CS21002769/4943

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Preli. Report

1) 10/3/13

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 2

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

MEROD

4417

10/3/13 P12 & 4417 confirmed with Jee/ (Car & 4611.50, 5110)

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/1CS01002769/UG43

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / SRim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) : \$ - RS. \$

) : Photos

) : Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee:

) : Site Insp (\$)

) : Interview (\$)

) : Tech. Invs (\$)

) : Weekend (\$)

02/3/21 @ 2.45pm report to Nicholas Chua via Messenger.
 02/3/21 @ 5.43.46pm Nicholas Chua informed C/A via Messenger.
 02/3/21 @ 5.41pm informed Joel C/A & EX: \$ 500 by email.



FALCON-AIR AUTO SERVICES PTE LTD
 CO. REG. No.: 1995-01140-D

LKK Auto Consultants hence notify

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

INSURER: **ECICS Limited (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	MPC20A0005490	Date of Loss:	01/03/2021
Vehicle Reg. No.:	SJN1515H	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	SHARON ONG HWEE CHENG		
Driver:	SHARON ONG HWEE CHENG		
Make/Model:	LEXUS NX300, 2.0 E 5DR SUV (4WD) EXECUTIVE (A)	Vehicle Reg. Date:	23/12/2019
Vehicle Colour:	SILVER		
Engine No:	8AR4217426	Chassis No:	JTJBARBZ902228523
Odometer:	23000 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Remarks:	VEHICLE IN WORKSHOP		
Present Location:	FALCON-AIR AUTO SERVICES PTE LTD (TAMPINES)		

not Ashwin
Lee
Take photo before repair.
5 days
51185 \$ 500? we're.
P/P \$

COST OF CLAIMS

	Amount
Parts	6,188.50
Miscellaneous Items	0.00
Labour	2,840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,028.50
+ GST 7.00% (S\$)	632.00
Nett Amount (S\$)	9,660.50

P/P \$ 4417 =

This claim is handled by: **JOEL NG**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 01 Mar 2021)**Parts:** M1-SUV LEXUS NX300 2.0 E 5DR SUV (4WD) EXECUTIVE (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*N/S FRONT DOOR LOWER GARNISH <i>grnd</i>	0.00	0.00	*180.00 F <i>✓</i>
2	1		*N/S REAR DOOR <i>3-5 27</i>	0.00	0.00	*900.00 F <i>✓</i>
3	1		*N/S REAR DOOR LOWER GARNISH <i>D'S</i>	0.00	0.00	*180.00 F <i>✓</i>
4	1		*N/S REAR DOOR ARCH GARNISH <i>D'S</i>	0.00	0.00	*125.00 F <i>✓</i>
5	1		*N/S REAR DOOR WEATHERSTRIP <i>11</i>	0.00	0.00	*150.00 F <i>X</i>
6	1		*N/S REAR DOOR RUBBER <i>SVC</i>	0.00	0.00	*90.00 F <i>X</i>
7	1		*REAR BUMPER <i>cut</i>	0.00	0.00	*550.00 F <i>✓</i>
8	1		*REAR BUMPER LOWER <i>11</i>	0.00	0.00	*300.00 F <i>X</i>
9	1		*REAR BUMPER CLIPS <i>1er</i>	0	0.00	*50.00 FS <i>✓</i>
10	1	<i>*</i>	*N/S REAR RIM <i>cut Local Repa 4005.00</i>	0.00	0.00	*2,700.00 F <i>X</i>
11	1		*N/S REAR FENDER ARCH GARNISH <i>SVC</i>	0.00	0.00	*90.00 F <i>X</i>
12	1		*N/S REAR BUMPER ARCH GARNISH <i>grnd</i>	0.00	0.00	*135.00 F <i>✓</i>
13	1		*N/S REAR BUMPER SIDE RETAINER <i>11</i>	0.00	0.00	*50.00 F <i>X</i>
14	1		*N/S REAR FENDER INNER SHIELD <i>11</i>	0.00	0.00	*85.00 F <i>X</i>
15	1		*N/S REAR FENDER INNER SHIELD CLIPS <i>11</i>	0	0.00	*50.00 FS <i>X</i>

F=Franchise part. S=SpcNett.

Sub Total (\$\$) **5,635.00**
+ Margin on L,N Items 10.00% (\$\$) **553.50**

Total Parts (\$\$) **6,188.50**

Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CHECK WIRING	New	50.00 20
2	TRANSFER DOOR PARTS	New	120.00 60
3	COMPUTERISED WHEEL ALIGNMENT	New	120.00 60
4	TRANSFER TYRE TO NEW RIM AND BALANCING	New	50.00 X
5	TO DIAGNOSE AND RESET DOOR MEMORY	New	250.00 80
6	INSTALL REVERSE SENSOR IN NEW BUMPER	New	80.00 40
7	TO RE-INITIALISE DOOR MEMORY AND REVERSE SENSOR	New	250.00 X
8	LABOUR/PANEL BEATING	New	800.00 600
9	SPRAY PAINTING	New	1,000.00 750
10	TO REMOVE/REFIT TRIMS AND GARNISHES	New	120.00 80
Gross Labour Cost (\$\$)			2,840.00

Falcon-Air Auto Services Pte Ltd/SJN1515H/01/03/2021 14:35. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >


1690

FALCON-AIR AUTO SERVICES PTE LTD

(a subsidiary of Falcon-Air Holdings Pte Ltd)

Head Office : Blk 176 Sin Ming Drive #01-06/07/13, #05-17 Sin Ming Autocare S(575721) Tel: 6452-0880 / 6458-0880 Fax: 6454-7862
Branches : Tampines St 93 Blk 9006 #01-200 S(528840) Tel: 6789-7997 Fax: 6788-7997 • No 8 Pandan Loop S(128226) Tel: 6779-5665 Fax: 6779-1110
Website: www.falconair.com.sg Email: email@falconair.com.sg

P-2070
+ 102
9-2277
S/N - 50.00
Repair S/N - 400
2 - 1690
4417



合興汽車零件私人有限公司 HE XING AUTO PARTS PTE LTD

MAIN OFFICE: No. 76 DUNLOP STREET, SINGAPORE 209403

TEL: 6291 2827 FAX: 6296 4390

A/C: 6291 1886 FAX: 6291 7717

Co. Reg. No: 200310923R GST Reg. No: 20-0310923-R

TAX INVOICE

M/S: FALCON-AIR AUTO SERVICES PTE LTD(TP)-2

BLK 9006 TAMPINES ST 93

#01-200

SINGAPORE 528840

NO: DLI9238415

PAGE: 1

DATE: 02/03/2021

A/C CODE: LDFA143

TERMS: CR

VEH NO: SJN1515H

Part No	Description	Location	Qty	Unit Price	Amount
				SIN	SIN
1 T75074-78010 ✓	MLDING LH	DU1G29	1	180.00	180.00
2 T67004-78020	DOOR RR LH	DB1A39	1	900.00	900.00
3 T75078-78010 ✓	MLDING LH	DU1F18-8	1	180.00	180.00
4 T52159-78908	RR BPER	DB3AA	1	550.00	550.00
5 T75606-78010 ✓	MLDING QTR LH	DU2D14	1	135.00	135.00
6 T75062-78010 ✓	MLDING RR DR LH	DU2D12	1	125.00	125.00
TOTAL QUANTITY:			6	TOTAL	SIN 2,070.00
				ADD GST @ 7%	144.90
				GRAND TOTAL	SIN 2,214.90

Print / LIM / 02/03/2021 12:39:15 PM

SALESMAN: LIM

This document is computer generated. No signature required.

GOODS SOLD ARE NOT RETURNABLE

E. & O. E.

GOODS RECEIVED BY

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	01/03/2021 09:56 (SGT)
Date of Accident	01/03/2021 06:53 (SGT)
Exact Location of Accident	Upper Changi Rd N, Singapore
Additional Location Information	UPP CHANGI ROAD NORTH FILTER LANE > PIE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN1515H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	SHARON ONG HWEE CHENG
NRIC No	SXXXX580C
Email Address	piyoh@hotmail.com
Mobile Phone No	(Phone) +65-82682725
Alternative Phone No	(Home) +65-82682725

VEHICLE PARTICULARS

Manufacturer	Lexus
Model	Nx300
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	ECICS
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	MPC20A0005490
Cover Note Number	-

DRIVER

Name of Driver	SHARON ONG HWEE CHENG
NRIC No	SXXXX580C
Date Of Birth	27/05/1978
Occupation	Indoor

Date Of Driving Pass	02/06/2005
Driving experience	15 YEARS AND 9 MONTHS
Gender	Female
Mobile Number	(Phone) +65-82682725
Alt. Phone Number	(Home) +65-82682725
Email Address	piyoh@hotmail.com
Address	BLK110 TANAH MERAH BESAR ROAD
Address complement	#03-66
Postcode	498844
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	JAIRUS TAN
Gender	Male

PASSENGER 2

Name	JAYDEN TAN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

AS PER SKETCH PLAN ATTACH.

ATTACHMENT(S)

Are accident photos available for attachment?	No
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SMC6892H
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-

Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	JOY LEE YUEN CHING
NRIC No	SXXXX737A
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This form must be **completed by the Policyholder and/or the Authorised Driver**
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GfA Records Management Centre established by the General Insurance Association of Singapore (GfA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GfA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages), and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GfA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims
 - (e) the information so collected under (d) above may be shared / disclosed
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature Date & Time

Driver's Signature
(If driver is not the policyholder) Date & Time

Reporting Centre Personnel's Signature
Name: 1/3/2021
NRIC/FIN No.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 01/01/2021 at 6:53pm I was driving along Upper Church Road North from the pit ^{road} as I was turning towards the main road in the pit my car collided with another car on my left driving car plate no. SJN 68921. The car suffered scratches on its front right number plate. The damages on my car were on the left front door door and bumper area. There were no physical injuries involved.

* Kindly take note that you have 14 days to revert to Own Insurance Claim (own damage).

Claim OD / TP At Falcon-Air	Claim OD / TP Own W/shop	Reporting Only
-----------------------------	--------------------------	----------------

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature Date & Time

Driver's Signature (if driver is not the policyholder) Date & Time


Reporting Centre Personnel's Signature Name: NRIC/ID No.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle**

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	580C
Vehicle Details	
Vehicle No.:	SJN1515H
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Mar 2021
Vehicle Make:	TOYOTA
Vehicle Model:	LEXUS NX300 5DR SUV (AT)(4WD) EXECUTIVE
Primary Colour:	Silver
Manufacturing Year:	2019
Engine No.:	8AR4217426
Chassis No.:	JTJBARBZ902228523
Maximum Power Output:	175.0 kW (234 bhp)
Open Market Value:	\$41,083.00
Original Registration Date:	24 Dec 2019
First Registration Date:	24 Dec 2019
Transfer Count:	0
Actual ARF Paid:	\$49,517.00 <i>WTS</i>
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	23 Dec 2029
PARF Rebate Amount:	\$37,137.00
Intended COE Rebate Details	
COE Expiry Date:	23 Dec 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,700.00
COE Rebate Amount:	\$34,961.00
Total Rebate Amount:	\$72,098.00

The information contained herein is correct as at 02 Mar 2021

OK



Post an Advertisement

Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Toyota Alphard 2.5A SC Moonroof.

Elegant Black MPV, "SC" Model With High Specifications.Auto Cruising Function.
Direct Owner StarAd

Think One Automobile

NEW & USED COMMERCIAL VEHICLES

Browse by Category

Sort by Date Posted

20 results/page

6 vehicles

Lexus NX300

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Lexus NX300		Any	Any	2019	Any	Any	Any	Available
	Lexus NX300	Lexus NX300 Luxury	\$173,800	\$16,390 /yr	27-Dec-2019	1,998 cc	19,000 km	SUV	Available
Special 1.88% Interest Rate! 1 Owner, High Spec Luxury Model, High ARF \$58320, Fully Maintained And 5 Years Warranty By Lexus Bor... Auto Zoom Enterprise Pte Ltd Posted: 02-Mar-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									
	Lexus NX300	Lexus NX300 Executive	\$156,800	\$15,310 /yr	17-Oct-2019	1,998 cc	22,788 km	SUV	Available
Consignment Unit! 1 Owner Only. Fully Maintained At Lexus Agent With Warranty Till Oct 2024. Bank And In House Full Loan Available.... Imperium Car Motor Pte Ltd Posted: 01-Mar-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									
	Lexus NX300	Lexus NX300 Luxury	\$157,999	\$16,280 /yr	28-Jan-2019	1,998 cc	36,000 km	SUV	Available
Just Arrived! Elegant White Unit, 1 Ownerships. 5 Years Borneo Motors Agent Warranty. Highest Spec Luxury Model With Panoramic Glas... Premium Automobiles Posted: 26-Feb-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									
	Lexus NX300	Lexus NX300 Executive	\$166,800	\$16,250 /yr	29-Nov-2019	1,998 cc	8,600 km	SUV	Available
1 Owner,Low Mileage Done Only 8,200Km,5 Years Unlimited Mileage Warranty By Lexus,100% Loan Available,Ex-Bankruptcy And Bad C... Faster Auto Trading Posted: 26-Feb-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									
	Genuine Lexus Car Shock Absorbers								
Genuine Parts for Lexus. Shock Absorbers and other related parts. More info about this product									
	Lexus NX300	Lexus NX300 Luxury	\$164,000	\$16,550 /yr	23-Apr-2019	1,998 cc	-	SUV	Available
Full Borneo Warranty & Serviced. High Spec Luxury Unit. All Time Reliable Lexus SUV. Selling Due To Owner Relocation. Inspection/Eval... Monster Motors Pte Ltd Posted: 18-Feb-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									
	Lexus NX300	Lexus NX300 Executive	\$165,000	\$16,250 /yr	18-Oct-2019	1,998 cc	7,000 km	SUV	Available
1 Owner. Very Low Mileage. 5 Years Warranty With Agent Borneo Motors. \$3000 More Free Servicing Package. Stunning Silver Metallic P... Posted: 27-Jan-2021 Tags: 2019 Lexus NX300, Lexus NX300, Lexus, NX300									

Save this search criteria, to get email alerts whenever a match is found.

Compare

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status