

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: GBC 7886P
 at Workshop m/s GOLD ARVO
 of 48 TOH HUAN RD GUST #01-119
 Insured: Min
 Policy No. _____
 Claims No. 4673095787SG
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

Bal. or Market Value: 48k
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 5 days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: GBC 7886P Yr Regn: 2016 MAR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: TOYOTA DYNA 150 M c.c. 2982
 Colour: ARBY A/C: Insured / Std / NI / NA
 Sp. Reading: 176186 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JFFAT35420K206072
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jaimmed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modi: NIP / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195R15Z
 R: 155R12C
 BS: BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 7 mm R/Bal. 5/5 mm
 L/Bal. 7 mm L/Bal. 5/5 mm
 D.O.A. 23/02/21 D.O.I. 02/03/21
 Survey held at GOLD ARVO
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair 1 unit = 25k</u>
	<u>Submit DAR; 5 repair days.</u>

Date/Time, File Pass to? ☐ : Prelt. Report ☐ : Final Report
 1) 04/03 Typist Date/Time, File Return to?
 2) _____
 Report Format: MER-DAR
 Lump Sum / I.C.F. (\$) _____
 Days Of Repair: 5
 Resurvey No. of Trip: _____
 Add Fee: ☐ : Site Insp (\$) ☐ : Interview (\$) ☐ : Tech. Invs (\$) ☐ : Weekend (\$) ☐ : Others
 Survey Fee: _____
 Transportation: _____ \$ + RS. _____
 Photos _____
 Others _____
 TOTAL _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/02/2021 16:28 (SGT)
Date of Accident 23/02/2021 13:45 (SGT)
Exact Location of Accident Singapore
Additional Location Information PIE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBE7886P

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner PRESTECH INDUSTRIAL AUTOMATION PTE LTD
Company Reg No 2XXXXX579Z
Email Address matt_tahir@yahoo.com
Mobile Phone No (Phone) +65-84241726
Alternative Phone No +65-84241726

VEHICLE PARTICULARS

Manufacturer Toyota
Model Dyna
Variant -
Exact purpose for which vehicle was being used at time of accident Employment
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Commercial vehicle

INSURANCE COMPANY

Name of Insurance Company Great Eastern
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 2020-V0111168-VCV
Cover Note Number -

DRIVER

Name of Driver SELAMAT BIN TAHIR
NRIC No SXXXXX529J
Date Of Birth 03/09/1970
Occupation Outdoor

Date Of Driving Pass	14/04/2009
Driving experience	11 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-84241726
Alt. Phone Number	-
Email Address	matt_tahir@yahoo.com
Address	BLK 218 AMK AVE 1 #09-911
Address complement	-
Postcode	560218
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Paid Driver
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	MR SNG
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SFG1868Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	HENG BARK LIAN
Contact Number	-


Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -


SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:



 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

COMBATDELGRD ENGINEERING PTE LTD
 320 UBI ROAD 3
 SINGAPORE 408641
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN

A: GBE 1886P

B: SFG 1868Z



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 23/5/2021 @ around 1345hrs I was travelling along PIB and was about to turn to Paya Lebar Rd. As there are many car turning the road was congested. All the vehicle are moving slowly to turn to Paya Lebar Rd exit. My vehicle was stationary and suddenly a blue Kia SFG 1868Z slam the rear of my vehicle.


DECLARATION

I/We declare the foregoing particulars are true in every respect:



Policyholder's Signature

Date & Time:



Driver's Signature

(If driver is not the policyholder)

Date & Time:

QUINFORD DELGRO ENGINEERING PTE LTD
320 1231 HOA W 7
SINGAPORE 418649

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	579Z
Vehicle No.:	GBE7886P
Vehicle to be Exported:	No
Intended Deregistration Date:	03 Mar 2021
Vehicle Make:	TOYOTA
Vehicle Model:	TOYOTA DYNA 150 MANUAL
Primary Colour:	Silver
Manufacturing Year:	2015
Engine No.:	1KD2588371
Chassis No.:	JTFAT35Y20K206072
Maximum Power Output:	-
Open Market Value:	\$24,944.00
Original Registration Date:	24 Mar 2016
First Registration Date:	24 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$1,248.00
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	23 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$44,477.00
COE Rebate Amount:	\$22,477.00
Total Rebate Amount:	\$22,477.00

The information contained herein is correct as at 03 Mar 2021

OK

X



Merimen e-Claims

X



Used 2016 Toyota Dyna 150 3.0M

X



art.com/used_cars/info.php?ID=956882&DL=3259

► Toyota Dyna 150 3.0M

Overview

Financial

Accessories

Similar

Research

Photos

Map



Price

\$48,800

Fuel Type

Diesel

Depreciation ?

\$9,440 /yr

View models with similar depre

Reg Date

03-May-2016

(5yrs 1mth 29days COE left)

Mileage

N.A.

Manufactured ?

2016

Road Tax ?

N.A.

Transmission

Manual

Dereg Value ?

\$20,454 as of today (change)

OMV ?

\$24,944

COE ?

\$39,585

ARF ?

\$1,248

Engine Cap

2,982 cc

No. of Owners ?

1

Curb Weight ?

1,760 kg

Type of Vehicle

Truck

Features

View specs of the Toyota Dyna 150 (2014)

D

Compare



VAN / LORRY (Rear)

48E 7886P

Rear Portion

NAC	INC	Item	CON	AC	Qty
1137	993626	Rear Number Plate			
1138	993627	Rear Number Plate Base			
2044	993628	Rear Number Plate Bracket			
1140	993632	Rear Number Plate Lamp			
1141	992958	Rear Bumper			
1142	993108	Rear Bumper Upper			
1143	993017	Rear Bumper Lower			
1144	993054	Rear Bumper Side			
1147	992976	Rear Bumper Bracket			
1148	993068	Rear Bumper Side Retainer			
1149	993045	Rear Bumper Reinforcement			
2045	993081	Rear Bumper Step Panel			
2046	993079	Rear Bumper Step Garnish			
2047	993186	Rear Crash Bar			
1158	994023	Reverse Sensor			
1159	993327	Rear End Panel			
1163	993851	Rear LH Taillamp			
1164	993853	Rear LH Taillamp Garnish			
1165	993859	Rear LH Taillamp Panel			
1166	995116	Rear RH Taillamp			
1167	993853	Rear RH Taillamp Garnish			
1168	993859	Rear RH Taillamp Panel			
1169	993554	Rear Apron Panel			
1289	995156	Rear LH Door			
1350	993201	Rear RH Door			
2048	991328	Rear Door Emblem			
2049	993274	Rear Door Outer Handle			
2050	993228	Rear Door Garnish			
2051	993294	Rear Door Rubber			
1291	995194	Rear LH Door Hinge			
1352	995307	Rear RH Door Hinge			
1301	993261	Rear LH Door Lock			
1362	993261	Rear RH Door Lock			
2052	993232	Rear Door Glass			
2053	993955	Rear Door Glass Sealant			
1248	994729	Third Brake Light			
1181	994543	Tailgate	bt	R	
2054	993700	Rear Rubber Stopper	cut		
2055	993701	Rear Rubber Stopper Bracket	bt		
1182	991328	Tailgate Emblem			
1183	994643	Tailgate Outer Handle			
1185	994545	Tailgate Garnish			
1193	994602	Tailgate Glass			
1194	994606	Tailgate Glass Rubber			
1195	994604	Tailgate Glass Moulding			
1196	994607	Tailgate Glass Sealant			
2056	994597	Tailgate Extension Mirror			
1197	994629	Tailgate Lock LH	bt		
1198	994651	Tailgate Rubber			
1199	994611	Tailgate Hinge	sc		1
1200	994594	Tailgate Damper			
1201	994613	Tailgate Inner Board			
2057	993992	Rear Wiper Arm			
2058	993995	Rear Wiper Blade			
2059	993997	Rear Wiper Motor			
2060	993484	Rear Floor Panel			
1204	995065	Spare Tyre			
2061	993785	Spare Tyre Bracket			
1212	993364	Rear Exhaust Pipe			
1214	993361	Rear Exhaust Mounting			
1216	995223	Rear LH Chassis Member			
1217	993165	Rear RH Chassis Member			

Vehicle No:

NAC	INC	Item	CON	AC	Qty
2062	993748	Rear Sidegate	bt	R	
2063	994225	Rear Sidegate Lock	bt		
2064	993749	Rear Sidegate Hinge	sc		1
2065	994226	Sidegate Lower Panel	bt		
2066	994227	Sidegate Railing			
2067	994208	Side Cover Hook			
2068	991965	Side Step Panel			
2069	994496	Side Step Panel Stopper			
2070	992857	Rear Body Panel			
2071	992866	Rear Body Panel Inner			
2072	995329	Sliding Door LH			
2073	995328	Sliding Door RH			
2074	994295	Sliding Door Handle			
2075	994300	Sliding Door Lock			
2076	994313	Sliding Door Rubber			
2077	994291	Sliding Door Bottom Roller			
2078	994317	Sliding Door Top Roller			
2079	994306	Sliding Door Rail			
2080	994315	Sliding Door Stepboard			
2081	994316	Sliding Door Stepboard Garnish			
1224	993621	Rear LH Mudflap			
1225	993933	Rear LH Wheel Rim			
1226	994025	Rear LH Rim Cover			
1227	995065	Rear LH Tyre			
1234	993622	Rear RH Mudflap			
1235	993934	Rear RH Wheel Rim			
1236	994025	Rear RH Rim Cover			
1237	995065	Rear RH Tyre			
1252	992179	Fuel Tank			
1253	992184	Fuel Tank Bracket			
1136	990247	Sticker	sc		

5 days