

Tanglin

CS3/CT121002806/Tiq.d3.

CoF 2022 May

Veh No: YL80269 Yr Regn: 2007/1 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mitsubishi FE85- C.C 2972

Colour white A/C: Insured / Std / NI / NA

Sp. Reading 479059 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: FF 83BFA / 0373

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

N/S	O/S
✓	✓

Tyre Size: F: 7.00 R16.

R: 185/R4 (D)

Front Rear

R/Bal.	6	mm	R/Bal.	6/6	mm
--------	---	----	--------	-----	----

L/Bal. 6 mm L/Bal. 6/6 mm

D.O.A. D.O.I. 2/3/21

Survey held at Garage 13.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

[illegible]

☐: Preli. Report

☐: Final Report

Days Of Repair: 9

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp (\$

☐: Interview (\$

☐ : Tech. Invs (8)

Weekend (8)

Survey Fee:

Transportation:

5) $S + RS \rightarrow SI$

1) Photos

) Others

TOTAL