

[Service Requests](#)[Messages](#)[Claims](#)

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	TPVD MERCEDES C 180 (SMF9464A)
Date of Loss	20 February 2021
Time of Loss	13:30
Loss Description	SMP7232M (INSD) C/W SMF9464A (TP)
Comment	

Workshop Details

Total Rebate Amount	0
Nett Loss Amount	\$0.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (TP)
Days of work completion *	20



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SMF9464A

Registration State

SINGAPORE

Mileage

96106

Purchase Date

DD/MM/YYYY



Registration Date *

06/02/2014



Age of Vehicle

7

CATEGORY

POLICY
INFORMATION

ASSESSMENT INFORMATION

Manufacturing
Year

2013

Driver Details

CATEGORY



FNOL INFORMATION

POST SURVEY
INFORMATION


Driver Name

LEE YIN FUNG

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Make	TPVD MERCEDES	<input type="text" value="MERCEDES BENZ"/>
Model	C 180	<input type="text" value="C 180 BLUEEFFICIENCY"/>
Type		<input type="text" value=""/>
Type of Paint		<input type="text" value=""/>
Chassis No		<input type="text" value="WDD2040312A929365"/>
Engine No		<input type="text" value="27491030133640"/>
Engine Capacity		<input type="text" value="1595"/>
Sum Insured		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Date of Birth	18 March 1975	<input type="text" value="DD/MM/YYYY"/> 
Age	46	
Occupation	Unknown	<input type="text" value=""/>
Education Qualification	Other	<input type="text" value=""/>
Driving Experience	0	
Driver License #		<input type="text" value=""/>
License Type		<input type="text" value=""/>
License Issue Date		<input type="text" value="DD/MM/YYYY"/> 

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Market Value		<input type="text" value="0"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
License Expiration Date		<input type="text" value="DD/MM/YYYY"/> 
Address	Not Entered By User, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="v"/>
Gender	Unknown	<input type="text" value="v"/>
Marital status	Unknown	<input type="text" value="v"/>
Identification #	SXXXX783B	<input type="text"/>



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

03/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver Excess

0

Condition of Vehicle at time of survey

General condition

Fair



Steering (Serviceable)

Yes

No

Footbrake
(Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair



Other Excess

0

Tyre Condition

Age of Tyres

Front Tyre Size

Front left side

Front right side

Spare wheel

Rear Tyre Size

Rear left side

Rear right side

225/45R17

GOODYEAR6mm

GOODYEAR6mm

225/45R17

GOODYEAR6mm

GOODYEAR6mm



Service Requests

Messages

Claims



Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text" value="0"/>	Salvage%	<input type="text" value="0"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Cash Loss	<div><div>Yes</div><div>No</div></div>	Part supplied by
Paint Material Ratio	<input type="text" value="80"/>			

A
X
A

Save



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio










Parts & Labour







Miscellaneous

Summary

Parts







Add		Approve		Deny		Submit All							
EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR DOOR RH	Dented	0	1919	No	0	10	0	0	1727.1
	0	1		REAR DOOR W/STRIP RH	Necessary	0	160.5	No	0	10	0	0	144.45
	0	1		REAR DOOR MOULDING RH	Necessary	0	117.7	No	0	10	0	0	105.93
	0	1		REAR RH DOOR INNER LOCK	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH FENDER	Dented	0	2241.2	No	0	10	0	0	2017.08
	0	1		REAR BUMPER	Deformed	0	1412.4	No	0	10	0	0	1271.16
	0	1		REAR BUMPER MOULDING	Necessary	0	445	No	0	10	0	0	400.5















EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR BUMPER RH SIDE HOLDER (A)	Broken	0	110	No	0	10	0	0	99
	0	1		REAR BUMPER RH HOLDER (B)	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR WINDSCREEN REPAIR KIT	Necessary	0	220	No	0	10	0	0	198
	0	1		RH REAR BUMPER SENSOR	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH WHEEL RIM	Damaged	0	910	No	0	10	0	0	819
	0	1		REAR RH WHEEL RIM CAP	Damaged	0	57	No	0	10	0	0	51.3
	0	1		REAR LOWER RH ARM (A)	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH LOWER ARM (B) 350	Bent	0	190	No	0	10	0	0	171
	0	1		REAR RH LOWER ARM (C) 450	Serviceable	0	0	No	0	10	0	0	0

EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT
	0	1		REAR RH LOWER ARM (D) 540	Bent	0	150	No	0	10	0	0	135
	0	1		REAR RH DRIVE SHAFT	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH BRAKE DISC	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH SHOCK ABSORBER	Serviceable	0	0	No	0	10	0	0	0
	0	1		REAR RH KNUCKLE	Bent	0	1432	No	0	10	0	0	1288.8
	0	1		REAR RH KNUCKLE BEARING	Damaged	0	288	No	0	10	0	0	259.2

Labour

Add	Approve	Deny	Submit All
-----	---------	------	------------

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		TO REMOVE & REFIT REAR W/SCREEN	0	120	0	0	Reviewing		
	0		REAR BUMPER SENSOR REFIT	0	30	0	0	Reviewing		
	0		ANTI RUST	0	40	0	0	Reviewing		

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
	0		UNDERCARRIAGE REAR RH REMOVE & REFIT	0	180	0	0	Reviewing		
	0		WHEEL ALIGNMENT	0	60	0	0	Reviewing		
	0		REAR RH DOOR GLASS REMOVE & REFIT	0	60	0	0	Reviewing		
	0		RESPRAY PAINTING DAMAGE AREAS	0	700	0	0	Reviewing		
	0		TO REPAIR ACC DAMAGE AREAS, FUEL BOX	0	900	0	0	Reviewing		
	0		REAR BOOT INTERIOR REMOVE & REFIX	0	60	0	0	Reviewing		
	0		WIRING FEE	0	30	0	0	Reviewing		



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition



Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add		Approve		Deny		Submit All	
EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	DAYS OF REPAIR : 7 DAYS	Reviewing	0	0		
	0	1 SET REAR BUMPER CLIP	Reviewing	0	35	NECESSARY	
	0	REAR RH TYRE	Deny	0	0	SERVICEABLE	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
	0	1 SET RIVET FOR DOOR INNER BOARD	Reviewing	0	30	NECESSARY	



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount	\$0.00	Adjusted Claim Amount	\$10,932.52
------------------------	--------	-----------------------	-------------

CATEGORY	ESTIMATE	ADJUSTED
Spare Parts		
Labour		
Spare Parts		
Miscellaneous		

Submit for Review



Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT

SR
NO

NAME

ACTION

ESTIMATED
AMOUNT

ADJUSTED
AMOUNT

COMMENT

REMOVE



0

FINAL
LUMP
SUM

Reviewing

0

8750





Service Requests

Messages

Claims



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Estimated Claim Amount

\$0.00

Adjusted Claim Amount

\$8,750.00

CATEGORY

ESTIMATE

ADJUSTED

Miscellaneous

Submit for Review