



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### General Details

Involving TPVD TOYOTA C-HR (SLT7807X)

Date of Loss 28 February 2021

Time of Loss 18.10

Loss Description SLT7807X (TP) CUT INTO INSD LANE AND HIT SHD3054J (INSD) REAR RIGHT

Comment

### Workshop Details

Total Rebate Amount 41723

Nett Loss Amount \$35,277.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work completion \* 20



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Vehicle & Driver Details



Vehicle Registration#	SLT7807X	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>10/11/2017</div> <div></div>
Mileage	<div>289648</div>	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2017</div>
Make	TPVD TOYOTA	<div>TOYOTA</div>

### Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TEO CHEE TAT	<div></div>
Date of Birth	5 October 1966	<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	Policy INFORMATION
	C-HR HYBRID 1.8S A
Type	<input type="text"/>
Type of Paint	<input type="text"/>
Chassis No	ZYX102045950
Engine No	2ZR8125127
Engine Capacity	1797
Sum Insured	0
Market Value	77000

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text"/>
Driving Experience	0	
Driver License #		<input type="text"/>
License Type		<input type="text"/>
License Issue Date		<input type="text"/> 
License Expiration Date		<input type="text"/> 

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	SXXXXX714D	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



## Assessment Details

General &amp; Workshop Details

Vehicle &amp; Driver Details

Vehicle Condition

Taxes &amp; Ratio

Parts &amp; Labour

Miscellaneous

Summary

### Detailed Assessment

Inspection Date \*

04/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/  
Unnamed Driver  
Excess

0

### Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake  
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

## Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="25"/>	Settlement%	<input type="text" value="100"/>

## Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save







SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT N/S HEADLAMP ASSY	Cracked	0	1804.3	No		25			1353.23	Reviewing
<input type="checkbox"/>		0	1		FRONT BUMPER	Buckled	0	830	No		25			622.5	Reviewing
<input type="checkbox"/>		0	1		FRONT LOWER BUMPER	Cut	0	515.4	No		25			386.55	Reviewing
<input type="checkbox"/>		0	1		FRONT N/S BUMPER SIDE RETAINER	Damaged	0	65.1	No		25			48.83	Reviewing
<input type="checkbox"/>		0	1		FRONT N/S FENDER	Repair	0	0	No		25			0	Deny
<input type="checkbox"/>		0	1		FRONT N/S FENDER ARCH GARNISH	Cut	0	175.1	No		25			131.33	Reviewing

Labour

Add

Approve

Deny

Submit All

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		REMOVE / RENEW THE ABOVE PARTS INCLUDING KNOCKING, WELDING ETC	0	300	0	0	Reviewing	
<input type="checkbox"/>		0		TO PUTTY & SPRAY PAINT ON ACCIDENT AFFECTED PORTION	0	400	0	0	Reviewing	
<input type="checkbox"/>		0		CHECK AND RECONNECT WIRING	0	15	0	0	Reviewing	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous





Summary

Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		
<input type="checkbox"/>		0	CLIP (20PCS)	Reviewing		40	NECESSARY	



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$3,297.44	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$2,542.44			
Labour		\$0.00		\$715.00			
Miscellaneous		\$0.00		\$40.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



# Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	2600		

Submit for Review