

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 26.02.2021

Time: 15:25:49

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305455735
 REGN NO : SHD4651D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 23.01.2020
 DATE/TIME IN : 26.02.2021 12:25
 ACCIDENT DATE : 26.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

1	04-01-0104-0596-G	PANEL ASSY-REAR DOOR LH#	1 L	1,789.90	20.00	1,431.92	R7
2	04-01-0104-2469-G	MOULDING ASSY-W/LINE RR D	1 L	166.20	20.00	132.96	LR
3	28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1 N	80.00	10.00	72.00	cut
4	04-01-0104-0600-G	MIRROR ASSY-OUTSIDE RR VI	1 L	1,391.70	20.00	1,113.36	R7

SUB-TOTAL : 2,750.24

NATURE

1	0 L	PANEL BEATING[repair rr fender Lh]	600.00	525
1	23-502	SPRAYPAINT ON AFFECTED AREA	550.00	500
2	20-02	TRANSFER OF DOOR REAR LH	120.00	X

SUB-TOTAL : 1,270.00

TOTAL : 4,020.24

NAME & SIGNATURE

AUTHORISED : YES / NO

SURVEYOR NAME & SIGNATURE

DATE: 27/2/21

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jia Lin 27/2/21 5:49 pm

UP 26/2/21 @ 5:00 pm

P/P Resurvey after repair

2-3 days

Tan Jia Lin @ Khairat