

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010070
 ADDRESS : CITYCAB PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65551188

JOB NO : 305455737
 REGN NO : SHC 829R
 MILEAGE : 000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G3)
 DATE OF REGN : 16.01.2020
 DATE/TIME IN : 26.02.2021 15:35
 ACCIDENT DATE : 26.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52	<i>con</i>	
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00	<i>out</i>	
0003	04-01-0104-0810-G	MOULDING ASSY-SIDE SILL R	1	290.00	20.00	232.00	<i>Ry</i>	
0004	04-01-0104-2698-G	LAMP ASSY-REAR COMB OUTSI	1	870.40	20.00	696.32	<i>out</i>	
0005	04-01-0104-0575-G	PANEL ASSY-QUARTER OUTER	1	1,768.30	20.00	1,414.64	<i>Ry</i>	
0006	04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16	<i>out</i>	1844.50
0007	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60	<i>ali</i>	20% 1475.60

SUB-TOTAL : 3,122.24

JOB NATURE

0000	PB	PANEL BEATING		1100.00		<i>875</i>	
0001	SP	SPRAYPAINT CHARGE		1000.00		<i>750</i>	
0002	17-01	CHECK ALL LIGHTING		20.00		<i>/</i>	
0003	20-00	TUFF COAT ON AFFECTED PARTS.		30.00		<i>x 47</i>	<i>1645</i>

\$3120.60
 03 days #