

# COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd  
59 Loyang Drive Singapore 508969  
Fax: 6546 8156

Our Job Ref No : 305455737  
Date : 02/03/21

## FINALIZATION FORM

To : LKK

Fax :

Attn : TAUFIKH

Vehicle Reg No. : SHC 829R

Date of Accident : 26/02/2021

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBN5167Y  
###
2. The finalized amount shall be:
 


(a) Spare Parts after List discount	<u>\$1,475.60</u>
(b) Labour Charges	<u>\$1,645.00</u>
<b>Total for Part-By-Part Repair Cost</b>	<b><u>\$3,120.60</u></b>
(c) Lumpsum Repair (if applicable)	
Total for Lumpsum repair cost after Less: <u>20%</u>	<u>                    </u>
<b>Final Lumpsum Repair cost</b>	<b><u>                    </u></b>

3. Estimated normal period for repairs: 3 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : *taufikh*

Name : JUMANI

Name : TAUFIKH

Tel : 62148315

Date : 17/3/21

Fax : 65468156

### For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	--	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

\_\_\_\_\_

\_\_\_\_\_

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010070  
 ADDRESS : CITYCAB PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65551188

JOB NO : 305455737  
 REGN NO : SHC 829R  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : IONIQ(G3)  
 DATE OF REGN : 16.01.2020  
 DATE/TIME IN : 26.02.2021 15:35  
 ACCIDENT DATE : 26.02.2021

## JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

0001	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0002	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0003	04-01-0104-2698-G	LAMP ASSY-REAR COMB OUTSI	1	870.40	20.00	696.32
0004	04-01-0104-0852-G	REFLECTOR/REFLEX ASSY-RR	1	41.45	20.00	33.16
0005	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10	22.00	20.00	17.60

SUB-TOTAL : 1,475.60

## JOB NATURE

0000	PB	PANEL BEATING				875.00
0001	SP	SPRAYPAINT CHARGE				750.00
0002	17-01	CHECK ALL LIGHTING				20.00

SUB-TOTAL : 1,645.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 02.03.2021

REPAIR ESTIMATE

Time: 14:54:47

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
CUSTOMER: 7010070  
ADDRESS : CITYCAB PTE LTD  
383 SIN MING DRIVE  
SINGAPORE SINGAPORE 575717  
65551188

JOB NO : 305455737  
REGN NO : SHC 829R  
MILEAGE : 0000000000  
MAKE : HYUNDAI  
MODEL : IONIQ(G3)  
DATE OF REGN : 16.01.2020  
DATE/TIME IN : 26.02.2021 15:3  
ACCIDENT DATE : 26.02.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 3,120.60

\_\_\_\_\_  
MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :

AUTHORISED : YES / NO