

Our Ref: CT0221/SHD3054J/CK(st)
Date: 08.04.2021



CHINA TAIPING INSURANCE CO (S)PTE L
3 ANSON ROAD #16-00
Singapore 079909

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Attn : Motor Claims Department

Without Prejudice

Mainline +65 6383 6280
Facsimile +65 6280 9755

Dear Sir/Madam

www.cdge.com.sg

Company Registration No: 199506048W

ACCIDENT ON 28.02.2021 INVOLVING SHD3054J & SLT7807X ALONG CLEMENCEAU AVE NEAR UE SQ

Workshops

We are the authorised repair workshop for Comfort Transportation Pte Ltd , the owner of vehicle No SHD3054J, which was involved in the captioned accident with your insured vehicle No SLT7807X.

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609286

Ubi
320 Ubi Road 3
Singapore 408649

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

The vehicle owner and the taxi hirer/driver concerned have requested and authorised us to assist them in presenting their claims against the party responsible for all applicable matters arising from the damage of the vehicle.

As the accident was caused by the negligent act of your insured driver, we are submitting these claims for your consideration on behalf of the claimants:

Taxi Owner's Claim :

1. Cost of Repairs		S\$	2,889.00
2. Loss of Rental	4 days x S\$ 110.67	S\$	442.68
3. Survey Report Fee		S\$	0.00
4. LTA Search Fee		S\$	7.49
5. GIA / Police Report Fee		S\$	0.00
6. Others		S\$	0.00

Hirer's Claim :

1. Loss of Income	4 days x S\$ 80.00	S\$	320.00
2. Others		S\$	0.00

[E&OE] **Total Claims** S\$ **3,659.17**

A copy each of the following supporting documents marked [X] is enclosed:

<input checked="" type="checkbox"/>	Original Repair Bill	<input checked="" type="checkbox"/>	Letter of Authority from Owner/Hirer/Operator
<input checked="" type="checkbox"/>	GIA/Police Report(s)	<input checked="" type="checkbox"/>	Rental Rate Letter
<input checked="" type="checkbox"/>	LTA/GIA Search Slip(s)	<input checked="" type="checkbox"/>	Downtime/Mileage Record
<input type="checkbox"/>	Survey Report / Bill	<input type="checkbox"/>	Witness Statement / Accident Scene Photo(s)
<input type="checkbox"/>	Driver's IC/DL/VL / Road Tax / Log Card / Certificate of Insurance		
<input type="checkbox"/>	Tow Chit / PIR / Hirer's IRAS / Others :		

Kindly look into the matter and let us hear from you on the settlement of our clients' claims as soon as possible.

Please note that it is a condition of any settlement reached that it shall be without prejudice to any personal injury claim (if any) of the taxi driver.

Yours sincerely
Catherine Koh
CDGE Claims Department
DID: 62148733

FAX: 62141843

Email: catherinekoh@cdge.com.sg

This is a computer-generated letter. No signature is required.

A member of

COMFORTDELGRO

LETTER OF AUTHORISATION

(NAF / PAF)

**ACCIDENT INVOLVING i 40 SHD3054J , SLT7807X
ALONG CLEMENCEAU AVE NEAR UE SQ.****ON 28-Feb-21 18:10**I / We **ONG KIM TECK** (Hirer) NRIC No.: **SXXXX142G**and/or **ONG BENG HONG** (Relief) NRIC No.: **SXXXX960Z**Taxi Number **SHD3054J**

hereby authorise ComfortDelGro Engineering Pte Ltd(CDGE):

1. To submit my/our claims for damages, costs and expense, including loss of earning (Pending successful recovery), loss of rental, medical fee and legal costs.
2. To have absolute discretion to agree to any settlement or compensation amount in respect of my/our claim against third party (except personal injuries and medical claims).
3. To sign Discharge Voucher on my/our behalf.
4. To accept any payment (claim proceeds) in respect of the claim against third party and payment by cheque shall be forward directly to CDGE in accordance with CDGE's instruction and made in favour of **"ComfortDelGro Engineering Pte Ltd"**.

Date **01-Mar-2021**Name of Hirer **ONG KIM TECK**
Hirer NRIC **SXXXX142G**

Signature :

Address **456A SENGKANG WEST ROAD #10-...
791456**Contact No. **97951818**Name of Relief **ONG BENG HONG**
Relief NRIC **SXXXX960Z**

Signature :

Address **407B FERVALE ROAD 15-11
792407**Contact No. **91919961**

GST REG. NO. M2-8921817-3

Workshops

TAX INVOICE

8010012

CHINA TAIPING INSURANCE CO (S)PTE LTD
SPRINGLEAF TOWER

3 ANSON ROAD #16-00
SINGAPORE 079909

CONTACT NO: 62222366

VEHICLE NO
SHD3054J

MAKE
HYUNDAI

MODEL
I40

DATE OF REG
14.07.2016

CHASSIS CODE
KMHLB41UMGU091891

NO/DATE
91552688 31.03.2021

JOB NO.
305456320

ODOMETER READING

JOB TYPE

Description : 3P 28.02.2021

Invoice for Lump Sum Repair

Total Lump Sum Repair Amt		2,700.00
Add GST @ 7.000 %		189.00
Total Invoice amount		2,889.00

Issued by : KATHERINETAN 01.04.2021 13:37:36
Repair Type : CLSO/57/57
Payment Type/Term : /Credit 30 days

- 1) WHILST TAKING ALL REASONABLE PRECAUTIONS AGAINST FIRE, THEFT OR ACCIDENTAL DAMAGE, THE COMPANY ACCEPTS NO RESPONSIBILITY FOR CARS OR OTHER PROPERTIES BELONGING TO CUSTOMERS AND VEHICLES ARE DRIVEN AND TESTED AT OWNERS' RISK.
- 2) CUSTOMERS SHALL INSPECT THEIR VEHICLES IMMEDIATELY UPON DELIVERY AND SHALL WITHIN 7 DAYS FROM SUCH DELIVERY GIVE NOTICE IN WRITING TO THE COMPANY OF ANY COMPLAINTS. OTHERWISE, THE VEHICLES WILL BE DEEMED TO HAVE BEEN ACCEPTED IN GOOD ORDER.
- 3) INTEREST OF 1% PER MONTH WILL BE CHARGED ON A DAY TO DAY BASIS IN RESPECT OF ANY AMOUNT DUE AND OWING TO THE COMPANY BY THE CUSTOMER AND NOT PAID ON THE DUE DATE OF PAYMENT (I.E. AFTER 30 DAYS FROM THE INVOICE) FOR THE PERIOD OF DEFAULT.
- 4) PLEASE EXAMINE THIS INVOICE IMMEDIATELY UPON RECEIPT AND ADVISE THE COMPANY OF ANY ERRORS OR DISCREPANCIES WITHIN 14 DAYS OF RECEIPT. IF THE COMPANY DOES NOT HEAR FROM THE CUSTOMER, THE COMPANY WILL TREAT THIS INVOICE AS CORRECT AND BINDING.

ComfortDelGro Engineering Pte Ltd

A member of **COMFORTDELGRO**

Head Office:
205 Braddell Road
Singapore 579701

Kindly note that no receipt shall be issued unless requested.

CUSTOMER'S COPY

ACCOUNT No.	INVOICE No.	AMOUNT	BANK/CHQ No.

Our Ref: CT21020476

Date: 07 April 2021



TO WHOM IT MAY CONCERN

Dear Sir/Madam

ACCIDENT ON 28/02/2021 @ 18:10 hrs
ALONG CLEMENCEAU AVE NEAR UE SQ.
INVOLVING SLT7807X

We refer to the above-mentioned accident and wish to inform that **Comfort Transportation Pte Ltd** is the registered owner of the taxi bearing vehicle registration number **SHD3054J** (the "Taxi"). The Taxi was hired to **ONG KIM TECK IC NO SXXXX142G** a registered hirer-operator of **Comfort Transportation Pte Ltd** at the time of occurrence of the aforementioned accident at a rental rate \$**110.67** per day (inclusive of GST).

Please be advised that the Taxi was insured with **AXA Insurance Singapore Pte Ltd** on a third party basis at the material time of the accident.

We wish to confirm that the aforesaid hirer-operator had obtained our permission to undertake repairs for damage on the Taxi arising from the said accident with a motor workshop of his choice.

Please liaise with the said hirer-operator or his authorized workshop directly for settlement of claims with third party's insurance company in respect of the said accident.

Yours faithfully

Philip Chia
Manager, Fleet Safety

This is a computer generated letter. No signature is required.

SHD 8052 J

DATE	NAME OF DRIVER	MILEAGE READING	MILEAGE TRAVELLED (KM)	HOURS OPERATED (TIME)		DATE	NAME OF DRIVER
				FROM	TO		
24/2/21	Kim Teck	545779	173	4:05	11:45		
24/2/21	Moore One	545930	160	14:10	20:40		
25/2/21	Kim Teck	546084	147	4:10	11:00		
26/2/21	Kim Teck	546244	158	4:03	11:05		
27/2/21	Kim Teck	546385	141	4:05	11:27		
28/2/21	Kim Teck	546385					
28/2/21	Albert One	546635	250	10:30	20:50		
01-3-21	Accident	17	1W	09:25			
01-3-21	Repair	17	0W	19:30			

Enquire Vehicle-Related Transaction History

Transaction History Details

Log Date/Time:	01 Mar 2021 / 11:10:48	Transaction Amount:	\$7.49
Asset Type:	Vehicle	Channel:	External Agency
Asset ID:	SLT7807X	Business Transaction Reference No.:	20210301111048340947
Transaction Type:	18.32 Insurance Enquiry (GIRO Payment)		
User ID:	ECENGCC0 - GOH CHENG CHUAN ANDREW CORNELIUS		

Search Date / Time: 28 Feb 2021 18:10:00
Insurance Company: CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

Information displayed is correct as at the log date and time.

Enquire Related Logs OK

S1103054]