

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	Re	ef:	CS/AGI21002847/Qvd3n2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	Da	ate:	14/05/2021	
			Co	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SGY 5333S	Veh. Inspected		SMV 9479Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10009208	Excess (\$)		0.00	
	Assign From	STANLEY LAI	Assign Date		02/03/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model	MERCEDES BENZ S350L	c.c		3498	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	WDD2211562A319215	Colour		BLACK	
	Odometer	112727 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3.						
		Size	Make		Balance	
	R/H Front Tyre	255/45 ZR18	FALKEN		6 mm	
	L/H Front Tyre	255/45 ZR18	FALKEN		6 mm	
	R/H Rear Tyre	255/45 ZR18	FALKEN		6 mm	
	L/H Rear Tyre	255/45 ZR18	FALKEN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/02/2021	Inspection Date		03/03/2021	
	Survey held at	CHEW GOON MOTOR				
		BLK 10 ANG MO KIO IND PARK 2A #01-15/16/17, AVE 5, AMK AUTOPOINT SINGAPORE 568047				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: