

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub,
2 Kaki Bukit Ave 2, #01-18
Singapore 417921
Tel No. : +65 6842 0051 / 6744 0510 Fax No. : +65 6741 0510
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

Our Ref: **SKW 619 P**
Your ref: **SLF 1479 Y**

03 March 2021

AUTO & GENERAL INSURANCE (S) PTE LTD
SINGAPORE SHOPPING CENTRE
190 CLEMENCEAU AVENUE #03-01
SINGAPORE 239924
Attn: Motor Claims Department

Dear Sir/Madam,

NAME OF CLAIMANT : CHEU LISHAN
VEHICLE NUMBER : SKW 619 P
YOUR INSURED VEHICLE NUMBER : SLF 1479 Y
ACCIDENT ON 02 Mar 2021 ALONG 438 ANG MO KIO AVE 10
AT ABOUT 13:24 HOURS

We refer to your email/fax dated **03 Mar 2021** informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment **LKK Auto Consultants Pte Ltd of Adrian Ling** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at:

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit Autohub
2 Kaki Bukit Avenue 2
#01-18
Singapore 417921

Contact Person:

6842 0051 / 6744 0510 (Melody)

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,



.....
N-51 AUTOMOTIVE PTE LTD

FOR SURVEYOR:

Please initial here after completion of pre-repair inspection. Thank you!
Appointed surveyor :

(Name & Signature) :

Date & Time of Inspection: