

ASS. REC. BY: Tau Jkh

REF: CG / ALG 21002888 / 71 83-1

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD  TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. 1777985441SG  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SBS6786C Yr Regn: 2014 Aug  
 Type: M.Car / M.Cycle /  Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Marebo Benz Citewo c.c 6374  
 Colour: Multi A/C: Insured / Std / NI / NA  
 Sp. Reading: 44702 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: WER 62868523 / 25 + (17)  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod:  Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 275/70R225  
 R: ~ ^ (17)

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

|     |     |
|-----|-----|
| N/S | O/S |
|     |     |

Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 3 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS WP  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT IN

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front Rear  
 R/Bal. 0 mm R/Bal. 8/8 mm  
 L/Bal. 8 mm L/Bal. 8/8 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 4/3/210340p  
 Survey held at SBS Bedok Depot  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
Frt N/S  
 The U/C / Chassis frame / Body Structure affected due to collision. 653M

| Date/Time       | Action / Instruction  |
|-----------------|---|
|                 | <u>W/S will inform cost of repair later.</u>                  |
| <u>25/05/21</u> | <u>Submit final fig \$1,832.00 (repair cost not conclude)</u> |
|                 |   |
|                 |   |
|                 |   |
|                 |   |

Date/Time, File Pass to?  : Preli. Report  
 1) 25/05 Typist  : Final Report  
 Date/Time, File Return to?  
 2) \_\_\_\_\_

Days Of Repair: 3  
 Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_  
 Transportation: \_\_\_\_\_  
 S + RS: \_\_\_\_\_ \$  
 Photos \_\_\_\_\_  
 Others \_\_\_\_\_  
 TOTAL \_\_\_\_\_

Rep. Format: MER-TP  
 Lump Sum / L.B.F. (P) \_\_\_\_\_