

CS3

ASS. REC. BY: Tang JH

REF: CS

ASM 21002912/71983

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD (TP/WS/TP RES / OD RES / EVA / INV / MV)

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. S1M034B3

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
<u>X</u>	<u>X</u>

Bal. or Market Value: \$82K.

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 14 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SMT9516K Yr Regn: 2020 July

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Avante c.c. 1591

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 7869 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KM PD84 CML 409507

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Kumho

Front R/Bal. 7 mm Rear R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. \_\_\_\_\_ D.O.I. 4/3/21 @1.30pm

Survey held at Alpha Car

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range!</u>
	<u>Estimate COR: \$13,000-\$15,000; 14 repair days</u>
	<u>Dismantle resurvey: 05/03/2021</u>
<u>15/04/21 @ 11.19am</u>	<u>revised to Jun Hong via Smart Claims.</u>
<u>15/04/21</u>	<u>Submit PRS.</u>

Date/Time, File Pass to?  : Preli. Report

15/04 Typist  : Final Report

Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 14

Resurvey No. of Trip: 2

Add Fee:  : Site Insp (\$ \_\_\_\_\_)

: Interview (\$ \_\_\_\_\_)

: Tech. Invs (\$ \_\_\_\_\_)

: Weekend (\$ \_\_\_\_\_)

Survey Fee:

Transportation:

\_\_\_\_ \$ + RS. \_\_\_\_ \$

Photos

Others

TOTAL

Rep. Format: SMART CLAIMS - PRS

Lump Sum / L.S.H. (\$) \_\_\_\_\_