

ASS. REC. BY: STEVE

REF: CS 3/II 19017409/ ~~He P3d~~

Special Instruction:

SURVAYOR: ~~Hade Am~~

ASSIGNMENT (Office)

4/3/2021 12:03 PM

From (Person): ~~Gabriel wae~~

of III

Date/Time: ~~3.10.19 11.35a.m~~

Estimated Cost: CARINE KEK PHER SER

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: GBH 9360K

Insured: SHC 8964E

at Workshop m/s N-51 Automobile

Tel: 68420051

of 2 Kaki Bukit Ave 2 #01-18

Policy No:

Claim No: MCT19100016/01

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 1.10.2019

CA / REV / REP. / REV 24 HRS

mp

H.O.D. Endorsement:

Date/Time: 3.10.19 11.35a.m

Person Contacted: Zi ting

Vehicle IN/OUT

Date/Time

Action/Instruction (X) Estimate

GBH 9360K - X

SHC 8964E - X

Dismantle: 15/10/19 0194pm

After repair: 18/10/19 1159Am

4/3/21

Submit LS \$2350 (Red 12,650,84%) , 4 days

ASS. REC. BY: H. ANN

REF: II

ASSIGNMENT

From: _____ Date: 14.10.2019

Veh No: GBH 9360K Yr Regn: 15/06/2005
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Estimated Cost: _____
OD: TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____
Make: 15424 NHR69E c.c. 3059

To Inspect Vehicle No: GBH 9360K
at Workshop m/s: N-51 Auto Motive
of 2 Kaki Bukit Ave 2 #01-17

Colour: Blue A/C: Insured / Std / NI / NA
Sp. Reading: 681705 km T/Radio: Insured / Std / NI / NA

Insured: _____
Policy No. _____

Eng/No: _____
C/No: JAA NHR69E57100091

Claims No. _____
Sum Insured: _____ Excess: _____

Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or _____

(Client's Record)
Make of Veh: 3.0p.m owner working

Brake: Inorder / Jammed / Leaked / Burnt or _____
Modi: Nil / (S/Rim) / STD A/Rim or _____

(Policy Condition)
Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
X	X

Tyre Size: F: 185/R14C
R: 185/R14C

Bal. or Market Value: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or _____

IDAC Accident Report: _____ Consistent?: Yes or No

Front: _____ Rear: _____
R/Bal. 5 mm → BR1068stone R/Bal. 515 mm → Aplus xr

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 5 mm → BR1068stone L/Bal. 515 mm → Aplus xr

Est. Repairs: 4 days Res.: Yes or No
Lum Sum: --- % 3 Val.: Yes or No

D.O.A. 1/10/19 D.O.I. 14/10/19 0901pm
Survey held at N-51 Auto

CA / REV / REP. / 24 HRS "up"
Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or +.
The U/C / Chassis frame / Body Structure affected due to collision.

Date: _____ Person Contacted: _____

Date / Time	Action / Instruction
	<u>7 3-4K GBH 9360K</u>
	<u>Raye - 2/15-25km (PRS case)</u>
	<u>repair days - 4 days</u>
	<u>MV - 8000</u>
	<u>PV - 3969</u>
	<u>NV - 4000</u>
	<u>RECEIVED 07 NOV 2019</u>
	<u>15/11/2019</u>

Date/Time, File Pass to? : Prel. Report
 1) : Final Report
 Date/Time, File Return to?
 2) _____
 Report Format: PRS.
 Lump Sum / I.B.C. (%) _____

Days Of Repair: _____
 Resurvey No. of Trip: 2

Add Fee: : Site Insp (\$) _____
 : Interview (\$) _____
 : Tech. Invs (\$) _____
 : Weekend (\$) _____

Survey Fee: 170
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others: 11
 TOTAL: 171

At the car the gear → PR23515

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	(Not Notified) Edit Reg		03 Oct 2019 00:00 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]	
Insured:			
Main Claimant:	EFFICIENT TOWING SERVICES, Co. Reg. No.: 53349344K		
Vehicle Reg. No.:	GBH9360K	Date of Loss:	01/10/2019 19:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	
Vehicle Reg. No. (Insured):	SHC8964E	Policy No. (Claimant):	
		Excess:	
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 14/10/2019]		
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail
There are no mail for this case.			

ALL ASSOCIATED TASKS		View All	Search Tasks	Create New Task	Complete				
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									


Summer Lee (LKK Auto)

From: Chio Ziting <ziting@n51.com.sg>
Sent: Thursday, 3 October, 2019 11:25 AM
To: Motor Claim - III
Cc: sur@lkkauto.com; Admin-D (LKKAuto); Sundari Nagarajan - III
Subject: Re: GBH9360K & SHC8964E - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS
Attachments: 9360.pdf

Dear All,

Please see attachment.

Regards,
Zi Ting
N-51 Automotive Pte Ltd
Office: 6842 0051
Fax: 6741 0510
www.n51.com.sg



On Thu, Oct 3, 2019 at 11:20 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm

This Pre-Repair Survey is on Without Prejudice Basis.

THIRD PARTY VEHICLE NO. : GBH9360K
III INSURED VEHICLE NO. : SHC8964E
DATE OF LOSS : 01.10.19

We acknowledge receipt of your email.

In compliance to Pre-Action Protocol for NIMA cases, we note that

We disagree to the list of motor surveyors that you have proposed.

Therefore, we have appointed our surveyor LKK AUTO CONSULTANTS to conduct the pre-repair survey.

This claim is handled by **Sundari**.

Please let us have your client's accident report and repair estimate for our appointed surveyor to conclude his report.

****We would like to conduct a re-survey after spray painting. Please contact our surveyor to arrange.**

****Surveyor kindly upload this assignment to Merimen.**

Thank You.

Best Regards,

Gabriel Wee



64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: 03 October, 2019 10:03 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Re: GBH9360K & SHC8964E - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir / Madam,

We refer to your list of motor surveyors proposed.

We do not agree to your list of motor surveyors.

Please see attached.

Thank you.

Regards,


Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg



On Thu, Oct 3, 2019 at 8:56 AM Motor Claim - III <motorclaim@iii.com.sg> wrote:

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

64 Cecil Street; #05 - IOB Building

Singapore 049711

Tel: 6347 6100, Ext – 248

From: Chio Ziting [mailto:ziting@n51.com.sg]

Sent: 02 October, 2019 4:34 PM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: GBH9360K & SHC8964E - NOTICE TO INSURER TO CONDUCT PRE-REPAIR INSPECTION WITHIN 2 WORKING DAYS

Dear Sir/Madam,

As per above subject,

Please refer attachment and:-

Kindly propose / provide your 10 surveyors

Thank you.

Regards,

Zi Ting

N-51 Automotive Pte Ltd

Office: 6842 0051

Fax: 6741 0510

www.n51.com.sg

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	344K
Vehicle Details	
Vehicle No.:	GBH9360K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	16 Oct 2019
Vehicle Make:	ISUZU
Vehicle Model:	NHR69E
Primary Colour:	Blue
Manufacturing Year:	2005
Engine No.:	4JG2231142
Chassis No.:	JAANHR69E57100091
Maximum Power Output:	-
Open Market Value:	\$19,399.00
Original Registration Date:	15 Jul 2005
First Registration Date:	15 Jul 2005
Transfer Count:	6
Actual ARF Paid:	\$970.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	14 Jul 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$26,709.00
COE Rebate Amount:	\$3,969.00
Total Rebate Amount:	\$3,969.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 16 Oct 2019

OK

Enquire Vehicle Transfer Fee

Vehicle Details

Vehicle No. GBH9360K	
Make / Model ISUZU / NHR69E	
Vehicle Type: B76 - Goods (Open) Recovery Vehicle	Vehicle Attachment 1: No Attachment
Vehicle Scheme: Normal	Chassis No. : JAANHR69E57100091
Propellant : Diesel	Engine No. : 4JG2231142
Motor No. : -	Engine Capacity : 3059 cc
Power Rating : -	Maximum Power Output : -
Maximum Laden Weight : 3500 kg	Unladen Weight : 2360 kg
Year Of Manufacture : 2005	Original Registration Date : 15 Jul 2005
Lifespan Expiry Date : -	COE Category : C - Goods Vehicle & Bus
PQP Paid : \$26,709.00	COE Expiry Date : 14 Jul 2020
Road Tax Expiry Date : 14 Jan 2020	PARF Eligibility Expiry Date : -
Inspection Due Date : 14 Jan 2020	Intended Transfer Date : 16 Oct 2019
CO2 Emission : -	CEV/VES Rebate Utilised Amount : -
CO Emission : -	HC Emission : -
NOx Emission : -	PM Emission : -

Fees To Be Paid For Transfer

Transfer Fees	\$25.00
Road Tax Renewal - 12 months (15 Jan 2020 to 14 Jul 2020)	

Message

The fees above do not include any late road tax fees, which apply if road tax or lay-up has expired. You can use the digital service Enquire Road Tax Payable to check if there are any late road tax fees. Any road tax that has been paid for the vehicle will be transferred to the next owner. This vehicle has a road tax Over Payment of \$218.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable. Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

Print

Save as PDF

Copy as Text

DOA - 1/10/19

MV - 8000

PV - 3969

NV - 4000

Behnam Samudra

"

OK →

CONNECTING CAR BUYERS & SELLERS.
We'll handle your loans, insurance & other paperwork for FREE. [Find out more](#)



Car Make / Model Year Reg Transmission Vehicle Type

Home > Used Cars > Direct Owners > Isuzu NHR69E (COE till 12/2020)

ISUZU NHR69E (COE till 12/2020)

Overview Accessories Similar Research Photos Map

Price	N.A.	Fuel Type	Diesel
Depreciation	N.A.	Reg Date	16-Dec-2005 (1yr 1mth 6days COE left)
Mileage	N.A.	Manufactured	2005
Road Tax	N.A.	Transmission	Manual
Dereg Value	N.A.	OMV	\$18,879
COE	N.A.	No. of Owners	3
Engine Cap	3,059 cc		
Curb Weight	1,490 kg		
Type of Vehicle	Truck		

Description
100% Loan Available. Vehicle In Good Condition.

Category
COE Car, Direct Owner Sale

Status
Expired

- Resources**
-  **Vehicle Evaluation**
Afraid of lemons? Request to have this car evaluated professionally. [Find out more](#)
 -  **Car Valuation - Free**
Find out the market value of your existing car for free. [Get started](#)

Posted on: 19-Nov-2016 | Last Updated on: 10-Dec-2016
Tags: Isuzu NHR69E, Isuzu nhr69e, 2005 Isuzu NHR69E, 2005 Isuzu nhr69e, Isuzu, NHR69E, nhr69e, Used Isuzu
Tags lead to available vehicles.



Compare Report Error
More Actions

Seller Information

We do not reveal seller's information for expired posts. Please click here for available cars for sale.

ESSENTIAL TRANSACTION FORMS

- Indemnity form
- Receipt
- Ownership Transfer
- Sales agreement
- Hand-over form

GET HELP WITH PAPERWORK



sgCarMart Connect handles your transaction paperwork - send us your completed Sales Agreement, and we'll help with Car Loans, Insurance, Payments & Ownership Transfer, FREE for all sgCarMart Advertised Vehicles.

[Upload your Sales Agreement](#)

[Read our 8 Step Guide for Direct Buyers & Sellers](#)

Recommended for you

1-6 of 18



What is VEP and how do you register for it



The new Supra is special in its own right



Car sharing with Smove just got better



Toyota unveils the all new Yaris



Car number plates and what they stand for



Toyota Owners please come in!

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Audi, Kia, Hyundai, Volkswagen, Mitsubishi & BMW. There are plenty of cars for sale, even for COE cars, OPC cars, vans, luxury cars, sports cars, SUV, MPV, hatchback or stationwagons. You can also buy from a car auction and look up car loans, financial services, low mileage cars, car brands, car insurance, carpark rates, car audio, car grooming, car rental, vehicle insurance, car insurance quotation, car blog, car accessories, car workshop & car sticker. Visit our partners for job openings, Singapore jobs, real estate properties for sale, facebook marketing, mower, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from auction and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

Follow sgCarMart.com

MSME19130691 / SME Motor Pte Ltd - Kaki Bukit
 ENTRY DATE & TIME: 02/10/2019 17:21
 SUBMITTED BY: Chia Pei Ying

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/10/2019 17:21
Date Of Accident	01/10/2019 19:50
Exact Location Of Accident	SLIP RD FROM ANG MO KIO INTO CTE/SLE (NEAR LAMP PO
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH9360K
Insured/Policyholder	
Name Of Registered Owner	EFFICIENT TOWING SERVICES
Co Reg No	53349344K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-85888877
Vehicle Particulars	
Manufacturer	ISUZU
Model	NHR69E
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	NO
Policy Number	GA433865
Cover Note Number	
Driver	
Name of Driver	HOE CHERH INN
NRIC No	S7827977Z
Date Of Birth	25/09/1978
Occupation	OUTDOOR
Date Of Driving Pass	18/12/1998
Driving Experience	20 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93397292
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 212A PUNGGOL WALK #12-727
Postcode	821212
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS DRIVING ON THE SLIP ROAD ENTERING INTO CTE/SLE, SINGLE LANE SINGLE CARRIAGE WAY. WHILE COMING TO THE GIVE WAY LINE, I BRAKED AND STOPPED TO GIVE WAY TO THE ONCOMING VEHICLE. SUDDENLY, AFTER A FEW SECONDS, I FELT A GREAT IMPACT FROM THE REAR OF MY VEHICLE. I ALIGHTED FROM MY VEHICLE AND REALISED IT WAS A VEHICL WITH LICENSE PLATE NUMBER (SHC8964E) COLLIDED ONTO THE REAR OF MY VEHICLE.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8964E
Vehicle Make/Model/Colour	
Details Of Properties	VEHICLE B
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF INJURED PERSON 1

Name	HOE CHERH INN
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	GBH9360K
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	
Address	
Postcode	

Sketch Plan Pg. 1

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the Information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Sketch Plan #2 Pg. 1

SKETCH PLAN

Vehicle A
- GBH 9360K

Vehicle B
- SHC 8964E



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving on the slip road entering into CTE/SLR, single lane single carriage way.

While coming to the give way line, I braked and stopped to give way to the on-going vehicle. Suddenly after a few seconds, I felt a great impact from the rear of my vehicle.

Alighted from my vehicle and realised it was a vehicle with licence plate number (SHC 8964E) collided to the rear of my vehicle.

Vehicle A - GBH 9360K
Vehicle B - SHC 8964E

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: *

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	13 Nov 2019 10:45 Edit Reg		03 Oct 2019 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	-, Co. Reg. No.: -								
Main Claimant:	EFFICIENT TOWING SERVICES, Co. Reg. No.: 53349344K								
Vehicle Reg. No.:	GBH9360K	Date of Loss:	01/10/2019 19:00 - :59 [170 Months and 16 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP	Policy/Cover Note No.:							
Vehicle Reg. No. (Insured):	SHC8964E	Policy No. (Claimant):							
		Excess:							
Repairer:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB, 417921 Kaki Bukit - Tel: 68420051								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pooi Chin Han Daniel]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by LEE HOCK ANN] ... [Final Rpt due 14/10/2019]								
ASSOCIATED MAIL RECEIVED		View All	Compose Case Mail						
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All	Search Tasks						
		Create New Task	Complete						
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH9360K
[SHC8964E]
TP
EFFICIENT TOWING SERVICES
Oct 1 2019 7:00PM
[-]
N-51 Automotive Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	18/10/19 08:55	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
2	18/10/19 08:56	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
4	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
5	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
6	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
7	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
8	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
9	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
10	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
11	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
12	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
13	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
14	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
15	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
16	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
17	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
18	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
19	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
20	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
21	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
22	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
23	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
24	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
25	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
26	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
27	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
28	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
29	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
30	18/10/19 08:56	General View		Load JPG	<input checked="" type="checkbox"/>					
31	18/10/19 08:57	General View		Load JPG	<input checked="" type="checkbox"/>					
32	18/10/19 08:57	General View		Load JPG	<input checked="" type="checkbox"/>					
33	18/10/19 08:57	General View		Load JPG	<input checked="" type="checkbox"/>					
34	18/10/19 08:57	General View		Load JPG	<input checked="" type="checkbox"/>					
35	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
36	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
37	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
38	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
39	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
40	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
41	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
42	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
43	21/10/19 11:09	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
45	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
46	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
47	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
48	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
49	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
50	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
51	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
52	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
53	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
54	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
55	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
56	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
57	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
58	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
59	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
60	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
61	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
62	21/10/19 11:09	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
63	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
64	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
65	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
66	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
67	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
68	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
69	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
70	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
71	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
72	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
73	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
74	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
75	21/10/19 11:10	Reinspection Photo		Load JPG <input checked="" type="checkbox"/>
76	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
77	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
78	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
79	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
80	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
81	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
82	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
83	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
84	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
85	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
86	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>
87	21/10/19 11:11	After Repair Photo		Load JPG <input checked="" type="checkbox"/>

Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/10/19 08:43	Singapore Accident Statement		Load PDF <input type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/III19017409/HCF3E2**Date:** 13/11/2019REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

Claimant
Vehicle No : GBH9360K**Insured Vehicle No :** SHC8964E

Date of Loss: 01/10/2019

Nature of Claim: TP Claim No: N/A

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **GBH9360K**

Make & Model: ISUZU NHR69E, 3.1 D (M)

Engine No: 4JG2231142

Reg. Date: 15/07/2005 (Man. Year: 2005)

Chassis No: JAANHR69E57100091

Colour: Blue

Odometer: 681705 km

Engine Capacity: 3059 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185 R14C

Rear Tyre Size: 185 R14C (D)

Front Left Side: Bridgestone 5 mm

Rear Left Side: APLUS 5/5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: APLUS 5/5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 03/10/2019

Date Inspected: 14/10/2019 Inspected At:

N-51 Automotive Pte Ltd (HQ)
BLK 2 KAKI BUKIT, #01-17/18 KAKI
BUKIT AUTOHUB
Singapore 417921

Estimated Period of Repair: 0.0 days

Adjuster: LEE HOCK ANN**Manager:** CELINE FONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 13 Nov 2019)

Parts: N/A ISUZU NHR69E 3.1 D (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for GBH9360K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >