

ASS. REC. BY:

REF: CS3/ASM21002923/Qvf3

Special Instruction:

Surveyor: SUN PIN ASSIGNMENT (Office)From (Person): TAN JUN HONG of AXA Date/Time: 3/3/2021 10:30 AM

Estimated Cost: _____ Bill to: _____

OD ☒ WS TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLS 6601J Insured: SH 6102Hat Workshop m/s SENG HWEE MOTOR Tel: 67555205of BLK 1018 YISHUN IND PK a #01-350Policy No: _____ Claim No: S1M034BO

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 01-03-2021
(Client's Record)

"WP"

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: 04-03-21 12.37P.M Person Contacted: MR KUEH Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SLS 6601J- ☒
	SH 6102H- NS/INC19010088/K1qd3n2 DOA :05/06/2019
8/3/21	Send IA via Smart Claim
8/3/21	Submit PRS, repair range \$3,000-\$4,000 (3 days)