



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

| | |
|------------------|----------------------------------|
| Involving | TPVD Toyota Vios (SJW713L) |
| Date of Loss | 28 February 2021 |
| Time of Loss | 15.45 |
| Loss Description | SHD3249P (INSD) C/W SJW713L (TP) |
| Comment | <input type="text"/> |

Workshop Details

| | |
|---------------------------|------------------------------------|
| Total Rebate Amount | <input type="text" value="13156"/> |
| Nett Loss Amount | -\$13,156.00 |
| Assigned Workshop | LKK AUTO CONSULTANTS PTE LTD (TP) |
| Days of work completion * | <input type="text" value="20"/> |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration# SJW713L

Purchase Date

Registration State

Registration Date *



Mileage

Age of Vehicle 10

| CATEGORY | POLICY INFORMATION | ASSESSMENT INFORMATION |
|--------------------|--------------------|-------------------------------------|
| Manufacturing Year | | <input type="text" value="2010"/> |
| Make | TPVD Toyota | <input type="text" value="TOYOTA"/> |
| | | <input type="text"/> |

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|---------------|------------------------------|---|
| Driver Name | MUHAMMAD HANIS BIN RASHID | <input type="text"/> |
| Date of Birth | | <input type="text" value="dd/mm/yyyy"/> |

| Model CATEGORY | Vios POLICY INFORMATION | VIOS E AUTO ASSESSMENT INFORMATION |
|-------------------|-------------------------------|--|
| Type | | <input type="text" value=""/> |
| Type of Paint | | <input type="text" value=""/> |
| Chassis No | | <input type="text" value="MR053HY9305156446"/> |
| Engine No | | <input type="text" value="1NZY047801"/> |
| Engine Capacity | | <input type="text" value="1497"/> |
| Sum Insured | | <input type="text" value="0"/> |
| Market Value | | <input type="text" value="0"/> |

| CATEGORY Age | FNOL INFORMATION 0 | POST SURVEY INFORMATION |
|-------------------------------|-----------------------|---|
| Occupation | Unknown | <input type="text" value=""/> |
| Education Qualification | Other | <input type="text" value=""/> |
| Driving Experience | 0 | |
| Driver License # | | <input type="text" value=""/> |
| License Type | | <input type="text" value=""/> |
| License Issue Date | | <input type="text" value="dd/mm/yyyy"/>  |
| License Expiration Date | | <input type="text" value="dd/mm/yyyy"/>  |

| CATEGORY | FNOL INFORMATION | POST SURVEY INFORMATION |
|------------------|----------------------------|--------------------------------|
| Address | SG, Singapore | <input type="text"/> |
| Address type | Personal Correspondence | <input type="text" value="▼"/> |
| Gender | Unknown | <input type="text" value="▼"/> |
| Marital status | Unknown | <input type="text" value="▼"/> |
| Identification # | TBC | <input type="text"/> |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

05/03/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

| | | | |
|-------------|---------------------------------|-------------|----------------------------------|
| Depr./Bttr% | <input type="text"/> | Salvage% | <input type="text"/> |
| Discount% | <input type="text" value="25"/> | Settlement% | <input type="text" value="100"/> |

Paint Labour/Material Ratio

| | | | |
|--------------------|---------------------------------|----------------------|---------------------------------|
| Paint Labour Ratio | <input type="text" value="20"/> | Paint Material Ratio | <input type="text" value="80"/> |
|--------------------|---------------------------------|----------------------|---------------------------------|

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts




Add

Approve

Deny

Submit All

| | EDIT | SR NO | QUAN TITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISC OUNT% | SALV AGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) |
|--------------------------|------|-------|-----------|----------|-----------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|------------|-----------|------------------|-----------------|----------------|
| <input type="checkbox"/> | | 0 | 1 | | REAR BUMPER | Deformed | 0 | 458 | No | | 25 | | | 343.5 | Reviewing |
| <input type="checkbox"/> | | 0 | 1 | | REAR BUMPER SIDE HOLDER RH | Necessary | 0 | 55.2 | No | | 25 | | | 41.4 | Reviewing |
| <input type="checkbox"/> | | 0 | 1 | | REAR BUMPER REFLECTOR RH | Cracked | 0 | 98.3 | No | | 25 | | | 73.73 | Reviewing |
| <input type="checkbox"/> | | 0 | 1 | | TAILLAMP RH | Cracked | 0 | 322.5 | No | | 25 | | | 241.88 | Reviewing |
| <input type="checkbox"/> | | 0 | 1 | | REAR RH FENDER INNER SHIELD | Serviceable | 0 | 0 | No | | 25 | | | 0 | Deny |

| | EDIT | SR NO | QUANTITY | MATERIAL | PART NAME | CONDITION | LIST PRICE (WORKSHOP) | LIST PRICE (SURVEYOR) | SUPPLEMENTARY PARTS | DEPR./ BTTR% | DISCOUNT% | SALVAGE% | ESTIMATED AMOUNT | ADJUSTED AMOUNT | ACTION (PARTS) |
|--------------------------|---|-------|----------|----------|-------------------------------|-------------|-----------------------|-----------------------|---------------------|--------------|-----------|----------|------------------|-----------------|----------------|
| <input type="checkbox"/> |  | 0 | 1 | | REAR RH WHEEL HUB C/W BEARING | Damaged | 0 | 481.9 | No | | 25 | | | 361.43 | Reviewing |
| <input type="checkbox"/> |  | 0 | 1 | | REAR RH SHOCK ABSORBER | Serviceable | 0 | 0 | No | | 25 | | | 0 | Deny |
| <input type="checkbox"/> |  | 0 | 1 | | REAR AXLE | Serviceable | 0 | 0 | No | | 25 | | | 0 | Deny |








Labour

Add

Approve

Deny

Submit All

| | EDIT | SR NO | REPAIR/REPLACE (LABOUR) | PART NAME | ESTIMATE LABOUR AMOUNT | ADJUSTED LABOUR AMOUNT | ESTIMATE PAINT AMOUNT | ADJUSTED PAINT AMOUNT | ACTION (LABOUR) | COMMENT |
|--------------------------|---|-------|-------------------------|---------------------------------------|------------------------|------------------------|-----------------------|-----------------------|-----------------|---------|
| <input type="checkbox"/> |  | 0 | | PANEL BEATING, REMOVE AND REFIT PARTS | 0 | 300 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | SPRAY PAINTING TO AFFECTED AREA | 0 | 400 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | WIRING CHECK | 0 | 30 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | TUFF COAT | 0 | 40 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | TO REMOVE REVERSE SENSOR | 0 | 50 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | TO REMOVE REAR UNDERCARRIAGE | 0 | 80 | 0 | 0 | Reviewing | |
| <input type="checkbox"/> |  | 0 | | TO PERFORM WHEEL ALIGNMENT | 0 | 80 | 0 | 0 | Reviewing | |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary





Add

Approve

Deny

Submit All

| | EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|--------------------------|------|-------|---------------------------------|-----------|------------------|-----------------|---------------|--------|
| <input type="checkbox"/> | | 0 | DAYS OF REPAIR : 4 DAYS | Reviewing | | 0 | | |
| <input type="checkbox"/> | | 0 | SET REAR BUMPER CLIPS | Reviewing | | 30 | NECESSARY | |
| <input type="checkbox"/> | | 0 | SET REAR RH FENDER INNER SHIELD | Deny | | 0 | NOT NECESSARY | |

| EDIT | SR NO | CLIPS NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
|--------------------------|---|---------------|-------------------------|---------------------|--------------------|------------------|---|
| | | | | | | | |
| | | | | | | | |
| <input type="checkbox"/> |  | 0 | REAR RH WHEEL RIM | Reviewing | 450 | CUT |  |
| <input type="checkbox"/> |  | 0 | REAR RH TYRE | Deny | 0 | NOT NECESSARY |  |



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

| General & Workshop Details | | Vehicle & Driver Details | Vehicle Condition | Taxes & Ratio | Parts & Labour | Miscellaneous | Summary |
|----------------------------|--|--------------------------|-------------------|-----------------------|----------------|---------------|---------|
| Estimated Claim Amount | | \$0.00 | | Adjusted Claim Amount | | \$2,521.94 | |
| CATEGORY | | ESTIMATE | | ADJUSTED | | | |
| Spare Parts | | \$0.00 | | \$1,061.94 | | | |
| Labour | | \$0.00 | | \$980.00 | | | |
| Miscellaneous | | \$0.00 | | \$480.00 | | | |

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

| Add | Approve | Deny | Submit All | | | | |
|--------------------------|---------|------|----------------|------------------|-----------------|---------|--------|
| EDIT | SR NO | NAME | ACTION | ESTIMATED AMOUNT | ADJUSTED AMOUNT | COMMENT | REMOVE |
| <input type="checkbox"/> | | 0 | FINAL LUMP SUM | Reviewing | 2000 | | |

Submit for Review