

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305456970 Via Fax : EMAIL
Date : 4-3-21 Your Insured : SJW 1629R
Time of Fax : _____ Date of Acc : 04-3-21

Attn: Motor Claims Department ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

D 3526P

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305456970
 REGN NO : SHD3526P
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 13.09.2018
 DATE/TIME IN : 04.03.2021 12:45
 ACCIDENT DATE : 04.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2270-G	EMBLEM-HYBRID	1	24.30	20.00	19.44
0002	04-01-0104-2271-G	EMBLEM-IONIQ	1	31.30	20.00	25.04
0003	28-01-0103-0005-A	REAR BOOT LOGO CTPL	1 N	30.00	2.00-	30.00
0004	28-01-0103-0006-A	REAR BOOT TEL NUMBER CTPL	1 N	30.00	0.20	30.00
0005	28-01-9999-2025-A	APP LOGO REAR BONNET CTPL	1 N	40.00	0.02-	40.00
0006	04-01-0104-2282-G	COVER-RR BUMPER#	1	459.40	20.00	367.52
0007	04-01-0104-2533-G	MOULDING ASSY-RR BUMPER C	1	451.25	20.00	361.00
0008	04-01-0104-1150-A	PROTECTOR MAT	1 N	50.00	2.00-	50.00
0009	04-01-0101-0111-G	BUMPER COVER CLIP REAR	10 L	22.00	20.00	17.60
0010	04-01-0104-2256-G	PANEL ASSY-TAIL GATE#	1	2,480.40	20.00	1,984.32
0011	04-01-0104-2175-G	SYMBOL MARK-H	1	28.00	20.00	22.40
0012	FNPS	NUMBER PLATE FRONT	1 N	25.00	2.00-	25.00
0013	09-01-0104-2133-G	ANTENNA ASSY-SMARTKEY	1	40.50	20.00	32.40

COMFORTDELGRO ENGINEERING PTE LTD

Date: 04.03.2021

REPAIR ESTIMATE

Time: 15:30:52

Page: 2

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305456970
REGN NO : SHD3526P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 04.03.2021 12:4
ACCIDENT DATE : 04.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

0014 04-01-0104-2370-G LAMP ASSY-REAR FOG 1 201.50 20.00 161.20

0015 05-01-0199-0032-A WINDSCREEN AHESIVE-310MLC 2 N 46.00 2.00- 46.00

SUB-TOTAL : 3,211.92

JOB NATURE

0000 PB PANEL BEATING 1100.00

0001 SP SPRAYPAINT CHARGE 600.00

0002 L RENEW REAR WINDSCREEN GLASS 120.00

0003 L REMOVE/REFIX REVERSE SENSOR 80.00

0004 17-01 CHECK ALL LIGHTING 50.00

SUB-TOTAL : 1,950.00

COMFORTDELGRO ENGINEERING PTE LTD

Date: 04.03.2021

Time: 15:30:52

REPAIR ESTIMATE

Page: 3

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305456970
REGN NO : SHD3526P
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 13.09.2018
DATE/TIME IN : 04.03.2021 12:4
ACCIDENT DATE : 04.03.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

TOTAL : 5,161.92

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :

Date/Time: 04.03.2021 15:14

Page : 1

JOB CARD

Team: ARC Repair TP(CLSO)1
OWNER

Sales Order:

JC NO.: 305456970

AS COMFORT TRANSPORTATION PTE LTD
OWNER NO. 7010045
RESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)
(P)


REGN NO.: SHD3526P	MILEAGE
MAKE: HYUNDAI	FUEL
MODEL	Engine 1/2.....F
YR OF MANU. IONIQ(G2)	DATE/TIME IN 04.03.2021 12:45
CHASSIS CODE 13.09.2018	TARGET DATE
KMHC851CVKU107562	COMPLETION DATE/TIME:

DUNT CARD NO.

JOB DESCRIPTION

Accident Date: 04.03.2021
NATURE: 3P 04.03.2021

S/N LABOR CODE DESCRIPTION



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

pledgement Slip

Exit Pass

Vehicle No.:

No. SHD3526P JU AIG

SHD3526P

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard